

Paper Handling Solutions 870 Highway 54 East Fayetteville, GA 30214-2219

Phone: 770-955-3770

Invoice

Invoice Number:

227098

Invoice Date:

May 31, 2019

Page:

1

Bill To:

Reischiling Press, Inc ATTN: Accounts Payable

3325 South 116th St., Ste 161

Tukwila, WA 98168

Check/Credit Memo No:

Credit card payments over \$2,500

fee.

Ship to:

Reischling Press Inc

ATTN: Ron Lair

1065 Big Shanty Road Ste 130

Kennesaw, GA 30144-7820

Customer ID ReiPre01		Customer PO		Phone #	Payment Terms			
		Robbi	e King	770-373 4106	Net Due			
Shipping Method			Sale	es Representative	Ship Date	Due Date		
0 10	·			Christopher M.	4/23/19	5/31/19		
Quantity			Descrip	tion	Unit Price	Extension		
4.50	6397 Service Travel	e work pe	erformed on	Horizon BQ470	98.00	441.00		

	Subtotal	516.00
	Sales Tax	020.00
	rvoice Amount Credit Applied	516.00
will incur a 3% processing	TOTAL	516.00



Paper Handling Solutions

870 Hwy 54 E

Fayetteville, GA 30215 Phone: 770-955-3770 Fax: 770-955-3743

www.paperhandlingsolutions.com

WORK ORDER

Work Order #

6397

Туре

Service Call

Priority
Payment Method

Medium

Start Date

Invoice

Reference #

4/23/2019

Agreement #

Project #

	SERVICE	SITE		BILL-TO SITE			WORK REQUESTED			
Reischiling Press, Inc Harold Washington 1065 Big Shanty Road Suite 130 Kennesaw, GA 30144 770- 373-4137				RPI / Reischiling Press, Inc ATTN: Accounts Payable 3325 S. 116th St., Suite 161 Seattle, WA 48168 404-228-8333			Requested by Robbie King - Prod MGR: 4/22 Robbie called; PUR unit #5 is having glue spikes in the spine glue (conf Tues 4/23)			
T. t. t.	•		SCHE							
Technic		uration		Date		e Range				
Chris		1.00	4/23	/2019		ntimed				
-	4.15				EQUIPM					
Equipme			Descri	iption		Manufa			Model	Serial Number
2267	Stan	dard B	Q 470		T A D	Standard /	Horizor	1 BQ-4	70	
Date	Technic	cian	Notes		LABO)K	Dillabi	- 04.	Billian Bata	8
issues. C and corre Side glue coming fr possibly Glue pot high caus which car between				Enot sticking and glue spike checked nipper table squareness ect size. Both checked good. It had a lot of bubbles in it from moisture in the glue could cause glue not adhere quickly. The height had to adjusted down to sing the book block to flare uses glue penetration in the sheets. Test good. Tavel Rate - RT			4.5	\$98.00 \$98.00 \$75.00	\$441.00	
					TOTA	LS				
								7	Total Materials	
									Total Labor	\$516.00
								S	ervice Charge	\$0.00
								Т	otal Sales Tax	\$0.00
									Total Charges	\$516.00
Customer S	Signature:	_						_		