

Dwyer R&D, Inc. 30405 SE 84th St., #267 Preston, WA 98050 206-851-6595

dwyerrandd@comcast.net

BILL TO RPI Inc. 3325 S. 116th St., Suite 161 Seattle, WA 98168 SHIP TO RPI Inc. 3325 S. 116th St., Suite 161 Seattle, WA 98168 Invoice 1086

DATE 05/18/2019 **TERMS** Net 30

DUE DATE 06/17/2019

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
05/06/2019	Service/Repair	Prism 78 - No knife travel, knife latch doesn't pull in. Checked cam switches, OK.	3.50	96.00	336.00T
05/06/2019	Mileage		60	0.39	23.40
05/07/2019	Service/Repair	Traced switch problem to screen controller. Replaced with used one. Customer provided parts.	3	96.00	288.00T
05/07/2019	Mileage		60	0.39	23.40
		SUBTOTAL			670.80
		TAX			62.40
		TOTAL			733.20
		TOTAL DUE			\$733.20