

Dwyer R&D, Inc. 30405 SE 84th St., #267 Preston, WA 98050 206-851-6595 dwyerrandd@comcast.net

BILL TO RPI Inc. 3325 S. 116th St., Suite 161 Seattle, WA 98168 **SHIP TO**RPI Inc.
3325 S. 116th St., Suite 161

Seattle, WA 98168

Invoice 1125

DATE 07/15/2019 **TERMS** Net 30

DUE DATE 08/14/2019

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT	
06/27/2019	Service/Repair	Prism 78 - machine stopping knife return, bypassed microcknife and clamp to enable circ Traced out all common relays travel. Problem persists.	cut cuits.	96.00	576.00T	
06/27/2019	Mileage		60	0.39	23.40T	
06/28/2019	Service/Repair	Rechecking all microswitches knife cam, knife latch, handw Suggest microcut replacemer Customer will exchange or re	heel. nt.	96.00	432.00T	
06/28/2019	Mileage		60	0.39	23.40T	
07/03/2019	Service/Repair	Corrected bypass knife circui check back with customer. M seems to be operating norma	achine	0.00	0.00	
		SUI	BTOTAL	1,054.80		
		TAX	<		105.48	
		TO	TAL		1,160.28	
		ТО	TAL DUE	\$1,160.28		