


OFFICIAL ACCIDENT REPORT



Report Number	ACC-2026-344109	Report Date	June 16, 2026 09:39
Accident Location	████████, ██████████ ██████████████, ████, ██████████████████████ ██████████	Emirate	UAE
Accident Severity	Moderate	GPS Coordinates	25.124526617168797,55.4256783 5413508
Authorized Estimate	AED 641.04	Coverage	80.0%
Claim ID	claim_owner_1781588344109	Workshop	Al Quoz Auto Works

1. Incident Context & Conditions

Time of Incident	09:36	Road Type	Dry road
Weather Condition	Clear / dry	Lighting	Daylight

Brief Description of Circumstances

The claimant's vehicle collided with another vehicle in front of them due to the other driver's sudden braking. The incident occurred when the claimant was unable to stop in time. The claimant's vehicle sustained damage as a result of the collision. The other vehicle was also damaged in the incident.

AI damage evidence (pre-assessment only): Light — Lamp Crack (80%); Door — Scratch (65%); Fender — Scratch (89%); Scratch (77%); Part Crack (75%); Glass Crack (60%)

2. Vehicle 1 (Reporting / Liable Party)

Plate Number	ABU DHABI 4/ 88432	Vehicle Responsibility	100% Liable
Make & Model	MERCEDES-BENZ MERCEDES-BENZ-SEDAN-TEST (2024)	Policy / Insurer	OIC-AD-1122334455 Oman Insurance Company
Chassis Number (VIN)	WDDZF8DBXRA765432	Mulkiya Expiry	15-SEP-2026
Driver / Owner	Ahmed Ali	Garage Assigned	Al Quoz Auto Works

Identified Damage Areas

Light — Lamp Crack (Moderate, 80%); Door — Scratch (Minor, 65%); Fender — Scratch (Minor, 89%); Scratch (Minor, 77%); Part Crack (Moderate, 75%); Glass Crack (Moderate, 60%)

3. Vehicle 2 (Affected Party)

Plate Number	Pending verification	Vehicle Responsibility	0% Liable
Make & Model	Third party — details pending	Notes	Yes — other vehicle

First Party Signature ■■■■■■■■ ■■■■■■ ■■■■■■ (■■■■■■■■)	Second Party Signature ■■■■■■■■ ■■■■■■ ■■■■■■ ■■■■■■ (■■■■■■■■)
AUTOVAULT Verification Authority ■■■■■■■■ ■■■■ ■■■■■■ ■■■■■■	