


OFFICIAL ACCIDENT REPORT



Report Number	ACC-2026-369071	Report Date	June 04, 2026 22:39
Accident Location	Fatimah Bint Asad Street, Al Sharjah, Sharjah Emirate		
Accident Severity	Moderate	GPS Coordinates	25.3644° N, 55.3950° E

1. Incident Context & Conditions

Time of Incident	2026-06-04	Road Type	Normal traffic — dry road
Weather Condition	Clear / dry	Lighting	Full artificial streetlight

Brief Description of Circumstances

The inspection detected: Light — Lamp Crack, Door — Scratch, Fender — Scratch, Scratch, Part Crack, Glass Crack. Safety-critical damage identified on Light — Lamp Crack, Glass Crack requires immediate attention.

Detected damage: Light — Lamp Crack: Lamp Crack (80.2% confidence); Door — Scratch: Scratch (65.1% confidence); Fender — Scratch: Scratch (88.7% confidence); Door — Scratch: Scratch (48.7% confidence); Scratch: Scratch (76.8% confidence); Part Crack: Part Crack (74.8% confidence); Part Crack: Part Crack (69.8% confidence); Glass Crack: Glass Crack (60.1% confidence)

2. Vehicle 1 (Reporting / Liable Party)

Plate Number	9/24567	Vehicle Responsibility	100% Liable
Make & Model	LEXUS LEXUS-SUV-TEST (2024)	Policy / Insurer	ADNIC-987654321 · ADNIC INSURANCE
Chassis Number (VIN)	JTHBK1GG7R1234567	Mulkiya Expiry	20-AUG-2026
Driver / Owner	Faizal Khan	Garage Assigned	ProFix Auto Center — Dubai

Identified Damage Areas

Light — Lamp Crack (Moderate, 80% confidence); Door — Scratch (Minor, 65% confidence); Fender — Scratch (Minor, 89% confidence); Door — Scratch (Minor, 49% confidence); Scratch (Minor, 77% confidence); Part Crack (Moderate, 75% confidence)

3. Vehicle 2 (Affected Party)

Plate Number	Pending verification	Vehicle Responsibility	0% Liable
Make & Model	Third party — details pending	Notes	Yes — other vehicle

4. Autovault AI Inspection Assessment

AI Health Score	48/100	Risk Level	High
-----------------	--------	------------	------

Damage Zones Detected	6	Overall Status	FAIL
Insurer Authorized Estimate	AED 796.88	Coverage	80%
Workshop	ProFix Auto Center — Dubai	Claim ID	claim_owner_1780598369071


OFFICIAL ACCIDENT REPORT



Assessment Parameters

Parameter	System Log / Analysis	Status
Impact Velocity Estimate	Calculated Delta-V: 18 km/h at incident time	Low Severity Impact
OBD-II Sensor Diagnostic	No powertrain error codes triggered. SRS (airbags) intact.	System Safe
Structural Integrity Check	YOLO dual-model mapping: no frame rail deformation flagged. Road condition	Roadway analysed with workshop verification

5. ACCIDENT DIAGRAM SIMULATION /



Second Party Signature