


OFFICIAL ACCIDENT REPORT



Report Number	ACC-2026-597796	Report Date	June 15, 2026 20:23
Accident Location	—	Emirate	UAE
Accident Severity	Moderate	GPS Coordinates	—
Authorized Estimate	AED 641.04	Coverage	80.0%
Claim ID	claim_owner_1781540597796	Workshop	—

1. Incident Context & Conditions

Time of Incident	19:57	Road Type	Dry road
Weather Condition	Clear / dry	Lighting	Dawn / dusk — reduced visibility

Brief Description of Circumstances

The vehicle was involved in a collision with another car. The incident occurred when the other vehicle collided with the insured vehicle. The circumstances of the accident are currently being reviewed. The damage to the vehicle has been reported.

AI damage evidence (pre-assessment only): Light — Lamp Crack (80%); Door — Scratch (65%); Fender — Scratch (89%); Scratch (77%); Part Crack (75%); Glass Crack (60%)

2. Vehicle 1 (Reporting / Liable Party)

Plate Number	ABU DHABI 4/ 88432	Vehicle Responsibility	100% Liable
Make & Model	MERCEDES-BENZ MERCEDES-BENZ-SEDAN-TEST (2024)	Policy / Insurer	OIC-AD-1122334455 Oman Insurance Company
Chassis Number (VIN)	WDDZF8DBXRA765432	Mulkiya Expiry	15-SEP-2026
Driver / Owner	Ahmed Ali	Garage Assigned	—

Identified Damage Areas

Light — Lamp Crack (Moderate, 80%); Door — Scratch (Minor, 65%); Fender — Scratch (Minor, 89%); Scratch (Minor, 77%); Part Crack (Moderate, 75%); Glass Crack (Moderate, 60%)

3. Vehicle 2 (Affected Party)

Plate Number	Pending verification	Vehicle Responsibility	0% Liable
Make & Model	Third party — details pending	Notes	Yes — other vehicle

First Party Signature

■■■■■■■■ ■■■■■■ ■■■■■■ (■■■■■■■■)

Second Party Signature

■■■■■■■■ ■■■■■■ ■■■■■■ (■■■■■■■■)

AUTOVAULT Verification Authority



AUTOVAULT AI Platform · Traffic Systems Integration · Generated for insurer and workshop adjudication.