

VEHICLE INSPECTION REPORT

AI-Powered Body + Engine Sound Analysis · May 31, 2026 at 17:55
Physical Defect Detection (7-class YOLO + Severity Model) + Engine Knock Audio Classification

VIN / Registration	SALWAZ2EU1RA987654	Mileage	45000
Make / Model	LAND ROVER LAND ROVER-SUV-TEST	Year	2024

Owner Pre-Inspection Checklist

Functional safety

Check	Result
Headlights	Pass
Tail / brake lights	Pass
Indicators	Pass
Reverse light	Pass
Horn	Pass
Wipers	Pass
Mirrors	Pass
Tyre tread	Pass
Tyre condition	Pass
Tyre pressure	Pass
Brake pedal	Pass
Handbrake	Pass
Seatbelts	Pass
Windscreen	Pass

Dashboard & OBD

Notes: AI: OBD requires scanner or dashboard photo with codes

Emissions / smoke

Idle: none · Under rev: none
AI: exhaust smoke not assessed from static photos


Compliance snapshot

Plate: 7/66321 · Registration: 05-NOV-2026 · Insurance: AXA Insurance UAE · Prior inspections: 8

Tasjeel readiness estimate: 92/100 — Advisory — some items need attention

- AI body scan: 1 damage type(s) detected

AI Vehicle Health Assessment



Risk Level	Medium	Overall Status	ATTENTION
------------	--------	----------------	-----------

Key Risk Factors:

- Safety-critical components affected: Detachment

AI Inspection Summary

The inspection detected: Detachment. Safety-critical damage identified on Detachment requires immediate attention.

Defect Analysis — Dual Model Results

Detachment ■ **Safety-Critical** (Moderate, 56.0% confidence)
Detached panel or component is a road safety hazard — secure or replace immediately.

AI Recommendations

1. Detached panel or component is a road safety hazard — secure or replace immediately.

Engine Sound Analysis

Engine Status	ENGINE HEALTHY	Confidence	73.19%
Verdict	clean	Duration	11.81s
Remarks	No knock detected. Engine sounds healthy. Continue regular maintenance schedule.		

Standard 7-Part Damage Checklist

Component	Defect Type / Severity	Confidence	Status
Bonnet	No Damage Detected	—	—
Bumper	No Damage Detected	—	—
Dickey	No Damage Detected	—	—
Door	No Damage Detected	—	—
Fender	No Damage Detected	—	—
Light	No Damage Detected	—	—
Windshield	No Damage Detected	—	—
Total Unique Parts/Types	1	Overall Status:	ATTENTION

Additional Damage Detections (Severity Model)

Damage Type	Confidence	Severity Tier
Detachment	56.0%	Moderate

Annotated Images — Dual Model Detections

Blue/green boxes = part detections; Purple boxes = severity-only detections



This report was generated using the unified MEHRA inspection pipeline: physical defect detection with a 7-class part model and severity model, engine sound knock classification, and Groq LLaMA 3.3 for report analysis. Results should be verified by a qualified technician.