

VEHICLE INSPECTION REPORT

AI-Powered Body + Engine Sound Analysis · May 31, 2026 at 19:22
Physical Defect Detection (7-class YOLO + Severity Model) + Engine Knock Audio Classification

VIN / Registration	SALWAZ2EU1RA987654	Mileage	45000
Make / Model	LAND ROVER LAND ROVER-SUV-TEST	Year	2024

Owner Pre-Inspection Checklist

Functional safety

Check	Result
Headlights	FAIL
Tail / brake lights	FAIL
Indicators	N/A — Not visible / not testable from photo
Reverse light	N/A — Not visible from this photo angle
Horn	N/A — Cannot test from photo
Wipers	N/A — Not visible in upload
Mirrors	—
Tyre tread	N/A — AI: tread depth not measurable from photo
Tyre condition	N/A — AI: tyres not fully visible — visual scan only
Tyre pressure	N/A — AI: inflation not verified from photo
Brake pedal	N/A — Cannot test from photo
Handbrake	N/A — Cannot test from photo
Seatbelts	N/A — Not visible in upload
Windscreen	N/A — AI: glass not fully assessed — check windscreen ...

Dashboard & OBD

Notes: AI: OBD requires scanner or dashboard photo with codes

Emissions / smoke

Idle: none · Under rev: none
AI: exhaust smoke not assessed from static photos


Compliance snapshot

Plate: 7/66321 · Registration: 05-NOV-2026 · Insurance: AXA Insurance UAE · Prior inspections: 9

Tasjeel readiness estimate: 68/100 — Not ready — address issues first

- Safety: Headlights (low & high beam) — fail
- Safety: Tail lights & brake lights — fail
- Safety: headlights — AI: detachment detected (e.g. lamp/trim separated)
- Safety: tailLights — AI: detachment near lighting assembly
- AI body scan: 1 damage type(s) detected

AI Vehicle Health Assessment



Risk Level	Medium	Overall Status	ATTENTION
------------	--------	----------------	-----------

Key Risk Factors:

- Safety-critical components affected: Detachment

AI Inspection Summary

The inspection detected: Detachment. Safety-critical damage identified on Detachment requires immediate attention.

Defect Analysis — Dual Model Results

Detachment ■ **Safety-Critical** (Moderate, 56.0% confidence)
Detached panel or component is a road safety hazard — secure or replace immediately.

AI Recommendations

1. Detached panel or component is a road safety hazard — secure or replace immediately.

Standard 7-Part Damage Checklist

Component	Defect Type / Severity	Confidence	Status
Bonnet	No Damage Detected	—	—

Bumper	No Damage Detected	—	—
Dickey	No Damage Detected	—	—
Door	No Damage Detected	—	—
Fender	No Damage Detected	—	—
Light	No Damage Detected	—	—
Windshield	No Damage Detected	—	—
Total Unique Parts/Types	1	Overall Status:	ATTENTION

Additional Damage Detections (Severity Model)

Damage Type	Confidence	Severity Tier
Detachment	56.0%	Moderate

Annotated Images — Dual Model Detections

Blue/green boxes = part detections; Purple boxes = severity-only detections



This report was generated using the unified MEHRA inspection pipeline: physical defect detection with a 7-class part model and severity model, engine sound knock classification, and Groq LLaMA 3.3 for report analysis. Results should be verified by a qualified technician.