

#### INTRODUCTION

This application note describes the communication between a microcontroller and MEAS Switzerland's MS56XX pressure sensor modules series using SPI and I2C protocol. In these code examples we explain: microcontroller initialization, commands construction and calculation of pressure and temperature from the obtained data. For more information on specific pressure and temperature algorithm please refer to the specific MS56xx sensor datasheet.

The code in these examples is developed for the ATMEL ATmega644p microcontroller. The compiler used is gcc from the WinAVR 20080610 bundle available freely on the Internet. All examples presented here can be implemented on any microcontroller with hardware implementation of the SPI and I2C protocol.

### SPI PROTOCOL C-CODE EXAMPLE

Figure below shows an easy way to use MS56xx sensors with the SPI bus. Please note a minimum of 100nF decoupling capacitor for the sensor and the PS pin (protocol select) connected to ground that defines the usage of the SPI protocol.




Figure 1: Circuit diagram of the hardware used for the SPI C-code testing



```
//!
//! @file an520_SPI.c,v
//! Copyright (c) 2009 MEAS Switzerland
//!
//!
//!
//! @brief This C code is for starter reference only. It is written for the
//! MEAS Switzerland MS56xx pressure sensor modules and Atmel Atmega644p
//! microcontroller.
//!
//! @version 1.0 $Id: an520_SPI.c, v 1.0
//!
//! @todo
//____ M A C R O S
#define TRUE 1
#define FALSE 0
#define F_CPU 4000000UL // 4 MHz XTAL
#define CMD_RESET
                   0x1E // ADC reset command
\#define CMD_ADC_READ 0x00 // ADC read command
\#define CMD_ADC_CONV 0x40 // ADC conversion command
#define CMD_ADC_D1 0x00 // ADC D1 conversion
#define CMD_ADC_D2 0x10 // ADC D2 conversion #define CMD_ADC_256 0x00 // ADC OSR=256
#define CMD_ADC_512 0x02 // ADC OSR=512 #define CMD_ADC_1024 0x04 // ADC OSR=1024
#define CMD_ADC_2048 0x06 // ADC OSR=2056
#define CMD_ADC_4096 0x08 // ADC OSR=4096
#define CMD_PROM_RD 0xA0 // Prom read command
#define csb_hi() (_SFR_BYTE(PORTA) &= ~_BV(3)) // setting CSB low
#define csb_lo() (_SFR_BYTE(PORTA) |= _BV(3)) // setting CSB high
//____INCLUDES
#include <stdio.h>
#include <util/delay.h>
#include <avr/io.h>
#include <math.h>
//____ DEFINITIONS
void spi_send(char cmd);
void cmd_reset(void);
unsigned long cmd_adc(char cmd);
unsigned int cmd_prom(char coef_num);
unsigned char crc4(unsigned int n_prom[]);
//**************
//! @brief send 8 bit using SPI hardware interface
//!
//! @return 0
//*************
void spi_send(char cmd)
                       // put the byte in the SPI hardware buffer and start sending
            SPDR= cmd;
            }
```



```
//*************
//! @brief send reset sequence
//! @return 0
//*************
void cmd reset(void)
                            // pull CSB low to start the command
     csb_lo();
     spi_send(CMD_RESET);
                           // send reset sequence
     _delay_ms(3);
                            // wait for the reset sequence timing
                             // pull CSB high to finish the command
     csb_hi();
}
//**************
//! @brief preform adc conversion
//!
//! @return 24bit result
//*************
unsigned long cmd_adc(char cmd)
{
     unsigned int ret;
     unsigned long temp=0;
     csb_lo();
                                               // pull CSB low
     spi_send(CMD_ADC_CONV+cmd);
                                               // send conversion command
     switch (cmd & 0x0f)
                                               // wait necessary conversion time
           case CMD_ADC_256 : _delay_us(900); break;
           case CMD_ADC_512 : _delay_ms(3); break; case CMD_ADC_1024: _delay_ms(4); break; case CMD_ADC_2048: _delay_ms(6); break;
           case CMD_ADC_4096: _delay_ms(10); break;
     }
     csb_hi();
                                         // pull CSB high to finish the conversion
     csb_lo();
                                         // pull CSB low to start new command
     spi_send(CMD_ADC_READ);
                                         // send ADC read command
     spi\_send(0x00);
                                         // send 0 to read 1st byte (MSB)
     ret=SPDR;
     temp=65536*ret;
                                         // send 0 to read 2nd byte
     spi_send(0x00);
     ret=SPDR;
     temp=temp+256*ret;
     spi\_send(0x00);
                                         // send 0 to read 3rd byte (LSB)
     ret=SPDR;
     temp=temp+ret;
                                         // pull CSB high to finish the read command
     csb_hi();
     return temp;
}
//***************
//! @brief Read calibration coefficients
//! @return coefficient
//**************
```



```
unsigned int cmd_prom(char coef_num)
      unsigned int ret;
     unsigned int rC=0;
     csb_lo();
                                          // pull CSB low
     spi_send(CMD_PROM_RD+coef_num*2);
                                          // send PROM READ command
                                          // send 0 to read the MSB
      spi\_send(0x00);
     ret=SPDR;
     rC=256*ret;
     spi_send(0x00);
                                          // send 0 to read the LSB
     ret=SPDR;
     rC=rC+ret;
                                          // pull CSB high
     csb_hi();
     return rC;
//***************
//! @brief calculate the CRC code for details look into AN521
//!
//! @return crc code
//*************
unsigned char crc4(unsigned int n_prom[])
     int cnt;
                                                // simple counter
                                                // crc reminder
     unsigned int n_rem;
      unsigned int crc_read;
                                                // original value of the crc
      unsigned char n_bit;
      n_rem = 0x00;
      crc_read=n_prom[7];
                                                //save read CRC
      n_prom[7] = (0xFF00 & (n_prom[7]));
                                                //CRC byte is replaced by 0
                                                // operation is performed on bytes
      for (cnt = 0; cnt < 16; cnt++)
            // choose LSB or MSB
            if (cnt%2==1) n_rem ^= (unsigned short) ((n_prom[cnt>>1]) & 0x00FF);
            else n_rem ^= (unsigned short) (n_prom[cnt>>1]>>8);
            for (n_bit = 8; n_bit > 0; n_bit--)
                  if (n_rem & (0x8000))
                     n_{rem} = (n_{rem} << 1) ^0x3000;
                  }
                  else
                  {
                     n_rem = (n_rem << 1);
     n_rem = (0x000F & (n_rem >> 12)); // // final 4-bit reminder is CRC code
      n_prom[7]=crc_read; // restore the crc_read to its original place
     return (n_rem ^ 0x00);
}
//**************
//! @brief main program
//!
//! @return 0
```



```
int main (void)
      unsigned long D1;
                                // ADC value of the pressure conversion
      unsigned long D2;
unsigned int C[8];
                                 // ADC value of the temperature conversion
                                // calibration coefficients
                                // compensated pressure value
      double P;
      double T;
                                // compensated temperature value
      double dT;
                                // difference between actual and measured temperature
      double OFF;
                                // offset at actual temperature
      double SENS;
                                // sensitivity at actual temperature
      int i:
      unsigned char n_crc; // crc value of the prom
                             // prepare the port A
      DDRA = 0xFE;
                                // SDO input
// I2C pins as input
      DDRB = 0xBF;
      DDRC = 0x00;
                                // prepare the port D, RX out and TX out;
      DDRD = 0x82;
      PORTA= 0 \times 10;
      PORTD= 0x20;
      //SPI settings:master, mode 0, fosc/4
      SPCR=(1<<SPE) | (1<<MSTR);</pre>
      //alternative SPI settings: master, mode 3, fosc/4
      //SPCR=(1<<SPE)|(1<<MSTR)|(1<<CPOL)|(1<<CPHA);
      cmd_reset();
                                               // reset the module after powerup
      for (i=0;i<8;i++) { C[i]=cmd\_prom(i);} // read calibration coefficients
      n_crc=crc4(C);
      while(TRUE)
                                 // loop without stopping
             D1=cmd_adc(CMD_ADC_D1+CMD_ADC_256);
                                                     // read uncompensated pressure
             D2=cmd_adc(CMD_ADC_D2+CMD_ADC_4096);
                                                     // read uncompensated temperature
             // calcualte 1st order pressure and temperature (MS5607 1st order algorithm)
             dT=D2-C[5]*pow(2,8);
             OFF=C[2]*pow(2,17)+dT*C[4]/pow(2,6);
             SENS=C[1]*pow(2,16)+dT*C[3]/pow(2,7);
             T = (2000 + (dT*C[6])/pow(2,23))/100;
             P=(((D1*SENS)/pow(2,21)-OFF)/pow(2,15))/100;
             // place to use P, T, put them on LCD, send them trough RS232 interface...
   return 0;
```



### 12C PROTOCOL C-CODE EXAMPLE

Figure below shows an easy way to use MS56xx sensors with the I2C bus. Please note a minimum of 100nF decoupling capacitor for the sensor and the PS pin (protocol select) connected to VDD that defines the usage of the I2C protocol. In this example the CSB is connected to ground which defines the I2C address to 0xEE.




Figure 2: Circuit diagram of the hardware used for the I2C C-code testing

```
//!
//! @file an520_I2C.c,v
//!
//! Copyright (c) 2009 MEAS Switzerland
//!
//!
//!
//!
//!
@brief This C code is for starter reference only. It is written for the
//! MEAS Switzerland MS56xx pressure sensor modules and Atmel Atmega644p
//! microcontroller.
//!
//! @version 1.0 $Id: an520_I2C.c,v 1.0
//!
//! @todo
```



```
_ M A C R O S
//__
#define TRUE 1
#define FALSE 0
                    4000000UL // 4 MHz external XTAL
#define F CPU
#define SCL_CLOCK 100000L
                                 // I2C clock in Hz
                                 // Module address write mode
#define ADDR_W 0xEF
                   0xEF
                                 // Module address read mode
#define ADDR_R
                              // ADC reset command
// ADC read command
// ADC conversion command
// ADC D1 conversion
// ADC D2 conversion
// ADC OSR=256
// ADC OSR=512
// ADC OSR=1024
// ADC OSR=2048
// ADC OSR=4096
#define CMD_RESET 0x1E
#define CMD_ADC_READ 0x00
#define CMD_ADC_CONV 0x40
#define CMD_ADC_D1 0x00
#define CMD_ADC_D2 0x10
#define CMD_ADC_256 0x00
#define CMD_ADC_512 0x02
#define CMD_ADC_1024 0x04
#define CMD_ADC_2048 0x06
#define CMD_ADC_4096 0x08
                                // ADC OSR=4096
#define CMD_PROM_RD 0xA0
                                // Prom read command
//____INCLUDES
#include <stdio.h>
#include <util/delay.h>
#include <util/twi.h>
#include <avr/io.h>
#include <math.h>
//____ DEFINITIONS
unsigned char i2c_start(unsigned char address);
void i2c_stop(void);
unsigned char i2c_write( unsigned char data );
unsigned char i2c_readAck(void);
unsigned char i2c_readNak(void);
void cmd_reset(void);
unsigned long cmd_adc(char cmd);
unsigned int cmd_prom(char coef_num);
unsigned char crc4(unsigned int n_prom[]);
//**************
//! @brief send I2C start condition and the address byte
//!
//! @return 0
//*************
unsigned char i2c_start(unsigned char address)
{
      unsigned char twst;
      TWCR = (1 << TWINT) | (1 << TWSTA) | (1 << TWEN); // send START condition
       while(!(TWCR & (1<<TWINT)));
                                                    // wait until transmission completed
       twst = TW_STATUS & 0xF8;// check value of TWI Status Register. Mask prescaler bits.
       if ( (twst != TW_START) && (twst != TW_REP_START)) return 1;
       TWDR = address;
                                                    // send device address
      TWCR = (1 << TWINT) | (1 << TWEN);
       // wait until transmission completed and ACK/NACK has been received
      while(!(TWCR & (1<<TWINT)));
       twst = TW_STATUS & 0xF8;
```



```
// check value of TWI Status Register. Mask prescaler bits.
     if ( (twst != TW_MT_SLA_ACK) && (twst != TW_MR_SLA_ACK) ) return 1;
     return 0:
}
//****************
//! @brief send I2C stop condition
//! @return none
//**************
void i2c_stop(void)
{
     /* send stop condition */
     TWCR = (1 << TWINT) | (1 << TWEN) | (1 << TWSTO);
     // wait until stop condition is executed and bus released
     while(TWCR & (1<<TWSTO)); //THIS MAKES PROBLEM FOR IS2402
//****************
//! @brief send I2C stop condition
//!
//! @return 0
//**************
unsigned char i2c_write(unsigned char data)
     unsigned char twst;
     TWDR = data; // send data to the previously addressed device
     TWCR = (1 << TWINT) | (1 << TWEN);
     while(!(TWCR & (1<<TWINT))); // wait until transmission completed
twst = TW_STATUS & 0xF8; // check value of TWI Status Register. Mask prescaler bits</pre>
     if( twst != TW_MT_DATA_ACK) return 1;
     return 0;
}
//***************
//! @brief read I2C byte with acknowledgment
//!
//! @return read byte
unsigned char i2c_readAck(void)
{
     TWCR = (1 << TWINT) | (1 << TWEA);
     while(!(TWCR & (1<<TWINT)));
     return TWDR;
}
//***************
//! @brief read I2C byte without acknowledgment
//!
//! @return read byte
unsigned char i2c_readNak(void)
     TWCR = (1 << TWINT) | (1 << TWEN);
     while(!(TWCR & (1<<TWINT)));
     return TWDR;
}
//****************
//! @brief send command using I2C hardware interface
//!
```



```
//! @return none
//**************
void i2c_send(char cmd)
      unsigned char ret;
     ret = i2c_start(ADDR_W); // set device address and write mode
      {\mbox{\footnote{issue} start}} condition, possibly no device found */
            i2c_stop();
      }
      else
      {// issuing start condition ok, device accessible
            ret=i2c_write(cmd);
            i2c_stop();
}
//***************
//! @brief send reset sequence
//!
//! @return none
//**************
void cmd_reset(void)
     i2c_send(CMD_RESET);
                                          // send reset sequence
                                          // wait for the reset sequence timing
     _delay_ms(3);
}
//**************
//! @brief preform adc conversion
//! @return 24bit result
//*************
unsigned long cmd_adc(char cmd)
      unsigned int ret;
     unsigned long temp=0;
      i2c_send(CMD_ADC_CONV+cmd);
                                                // send conversion command
      switch (cmd & 0x0f)
                                                // wait necessary conversion time
            case CMD_ADC_256 : _delay_us(900); break;
            case CMD_ADC_512 : _delay_ms(3); break;
case CMD_ADC_1024: _delay_ms(4); break;
                                          break;
            case CMD_ADC_2048: _delay_ms(6);
            case CMD_ADC_4096: _delay_ms(10); break;
      i2c_send(CMD_ADC_READ);
      ret = i2c_start(ADDR_R);
                                                // set device address and read mode
      if ( ret )
      {//failed to issue start condition, possibly no device found
            i2c_stop();
      }
      else
      {//issuing start condition ok, device accessible
            ret = i2c_readAck();
                                                // read MSB and acknowledge
            temp=65536*ret;
            ret = i2c_readAck();
                                                // read byte and acknowledge
       temp=temp+256*ret;
            ret = i2c_readNak();
                                                // read LSB and not acknowledge
            temp=temp+ret;
            i2c_stop();
                                                // send stop condition
      }
```



```
return temp;
//*************
//! @brief Read calibration coefficients
//!
//! @return coefficient
//*************
unsigned int cmd_prom(char coef_num)
{
     unsigned int ret;
     unsigned int rC=0;
     // set device address and read mode
     ret = i2c_start(ADDR_R);
     if ( ret )
     {//failed to issue start condition, possibly no device found
          i2c_stop();
     else
     {//issuing start condition ok, device accessible
          rC=256*ret;
                                   // read LSB and not acknowledge
          ret = i2c_readNak();
          rC=rC+ret;
          i2c_stop();
     return rC;
//***************
//! @brief calculate the CRC code
//! @return crc code
//*************
unsigned char crc4(unsigned int n_prom[])
                                     // simple counter
     int cnt;
     unsigned int n_rem;
                                     // crc reminder
                                     // original value of the crc
     unsigned int crc_read;
     unsigned char n_bit;
     n_rem = 0x00;
                                     //save read CRC
     crc_read=n_prom[7];
     n_prom[7]=(0xFF00 & (n_prom[7]));
                                     //CRC byte is replaced by 0
     for (cnt = 0; cnt < 16; cnt++)
                                          // operation is performed on bytes
     {// choose LSB or MSB
          if (cnt%2==1) n_rem ^= (unsigned short) ((n_prom[cnt>>1]) & 0x00FF);
          else n_rem ^= (unsigned short) (n_prom[cnt>>1]>>8);
          for (n_bit = 8; n_bit > 0; n_bit--)
             if (n_rem & (0x8000))
               n_{rem} = (n_{rem} << 1) ^ 0x3000;
              }
              else
               n_rem = (n_rem << 1);
          }
     }
                                    // final 4-bit reminder is CRC code
     n_rem= (0x000F & (n_rem >> 12));
```



```
n_prom[7]=crc_read;
                                           // restore the crc_read to its original place
       return (n_rem ^ 0x0);
}
//***************
//! @brief main program
//!
//! @return 0
//**************
int main (void)
{
      unsigned long D1; // ADC value of the pressure conversion
                                  // ADC value of the temperature conversion
      unsigned long D2;
                                 // ADC value of the temperature conversion
// calibration coefficients
// compensated pressure value
// compensated temperature value
// difference between actual and measured temperature
// offset at actual temperature
// sensitivity at actual temperature
      unsigned int C[8];
      double P;
      double T;
      double dT;
      double OFF;
      double SENS;
      int i:
      unsigned char n_crc;
                                // crc value of the prom
       // setup the ports
       DDRA = 0xFE;
       DDRB = 0 \times 0 F;
                                  //SPI pins as input
       DDRC = 0x03;
                                  // I2C pins as output
       DDRD = 0x82;
                                   // RS out and tx out;
       PORTA = 0x1F;
                                  // I2C pin high
       PORTB = 0xF0;
       PORTC = 0x01;
       PORTD = 0x00;
       // initialize the I2C hardware module
       TWSR = 0;
                                                  // no prescaler
       TWBR = ((F_CPU/SCL_CLOCK)-16)/2;
                                                  // set the I2C speed
       D1=0;
       D2=0;
                                                  // reset IC
       cmd_reset();
       for (i=0;i<8;i++) { C[i]=cmd_prom(i);}</pre>
                                                  // read coefficients
       n_crc=crc4(C);
                                                  // calculate the CRC
                                                  // loop without stopping
       for(;;)
       {
              D2=cmd_adc(CMD_ADC_D2+CMD_ADC_4096);
                                                           // read D1
              D1=cmd_adc(CMD_ADC_D1+CMD_ADC_4096);
              // calcualte 1st order pressure and temperature (MS5607 1st order algorithm)
              dT=D2-C[5]*pow(2,8);
              OFF=C[2]*pow(2,17)+dT*C[4]/pow(2,6);
              SENS=C[1]*pow(2,16)+dT*C[3]/pow(2,7);
              T=(2000+(dT*C[6])/pow(2,23))/100;
              P = (((D1*SENS)/pow(2,21)-OFF)/pow(2,15))/100;
              // place to use P, T, put them on LCD, send them trough RS232 interface...
    return 0;
```

### **CRC CODE NOTES**

The CRC code is calculated and written in factory with the LSB byte in the prom  $n_{prom[7]}$  set to 0x00 (see Coefficient table below). It is thus important to clear those bytes from the calculation buffer before proceeding with the CRC calculation itself:

```
n_prom[7] = (0xFF00 & (n_prom[7])); //CRC byte is replaced by 0
```

As a simple test of the CRC code, the following coefficient table could be used:

```
unsigned int nprom[] = \{0x3132, 0x3334, 0x3536, 0x3738, 0x3940, 0x4142, 0x4344, 0x4500\};
```

the resulting calculated CRC should be 0xB.

A d d	D B 1 5	D B 1 4	D B 1 3	D B 1 2	D B 1	D B 1 0	D B 9	D B 8	D B 7	D B 6	D B 5	D B 4	D B 3	D B 2	D B 1	D B 0
0	16 bit reserved for manufacturer															
1	Coefficient 1 (16 bit unsigned)															
2	Coefficient 2 (16 bit unsigned)															
3		Coefficient 3 (16 bit unsigned)														
4		Coefficient 4 (16 bit unsigned)														
5		Coefficient 5 (16 bit unsigned)														
6	Coefficient 6 (16 bit unsigned)															
7									0	0	0	0		CF (0)	₹C (0)	·

Table 1: Memory PROM mapping



#### **REVISION HISTORY**

Date	Revision	Type of changes
18.06.2009	00	Initial document
12.01.2010	01	Change to MEAS logo and layout; addition of CRC code notes

#### **FACTORY CONTACTS**

#### **NORTH AMERICA**

Measurement Specialties, Inc. 1000 Lucas Way Hampton, VA 23666 Tel: +1 800 555 1551 Fax: +1 757 766 4297

e-mail: <u>sales@meas-spec.com</u> Website: <u>www.meas-spec.com</u>

#### **EUROPE**

MEAS Switzerland SA Ch. Chapons-des-Prés 11 CH-2022 Bevaix Tel: +41 32 847 9550

Fax: + 41 32 847 9569 e-mail: sales@intersema.ch Website: www.intersema.ch

#### **ASIA**

Measurement Specialties (China), Ltd. No. 26 Langshan Road Shenzhen High-Tech Park (North) Nanshan District, Shenzhen, 518107 China

Tel: +86 755 3330 5088 Fax: +86 755 3330 5099 e-mail: pfc.cs.asia@meas-spec.com Website: www.meas-spec-.com

The information in this sheet has been carefully reviewed and is believed to be accurate; however, no responsibility is assumed for inaccuracies. Furthermore, this information does not convey to the purchaser of such devices any license under the patent rights to the manufacturer. Measurement Specialties, Inc. reserves the right to make changes without further notice to any product herein. Measurement Specialties, Inc. makes no warranty, representation or guarantee regarding the suitability of its product for any particular purpose, nor does Measurement Specialties, Inc. assume any liability arising out of the application or use of any product or circuit and specifically disclaims any and all liability, including without limitation consequential or incidental damages. Typical parameters can and do vary in different applications. All operating parameters must be validated for each customer application by customer's technical experts. Measurement Specialties, Inc. does not convey any license under its patent rights nor the rights of others.