Kia Authorised Service Centre - Chennai

12, Anna Salai, Chennai, Tamil Nadu - 600002 | Ph: 044-28451190 | GSTIN: 33AAKCK5678M1Z4

VEHICLE REPAIR ESTIMATION SLIP

Job Card No.: JC-CHN-2026-5127	Date: 23 July 2026

CUSTOMER & VEHICLE DETAILS

Customer Name:

Vijay M

Vehicle:

Kia Seltos HTX Plus

Registration No.:

TN-12-AJ-1603

Odometer Reading:

24,680 km

Insurance / Policy No.:

Ganit Motors Insurance / POL-112233

#	Part / Service Description	Work Type	Qty	Source	Amount (Rs.)
1	Front Bumper Assembly (OEM)	Replace	1	OEM	5,800
2	Bonnet / Hood Panel (OEM)	Replace	1	OEM	11,800
3	Front Grille Assembly (OEM)	Replace	1	OEM	3,200
4	Headlight Assembly RH (OEM)	Replace	1	OEM	7,900
5	Front Right Fender	Repair + Paint	1	OEM	2,800
6	Radiator Assembly (OEM)	Replace	1	OEM	6,100
7	Labour - Panel Beating, Denting & Fitment	Labour	1	-	4,800
8	Labour - Painting (2-coat oven finish, 4 panels)	Labour	1	-	3,600

Sub-Total	Rs. 46,000
CGST @ 9%	Rs. 4,140
SGST @ 9%	Rs. 4,140
GRAND TOTAL	**Rs. 54,280**

Note: Severe front-right impact damage from a head-on collision with a roadside barrier. All parts OEM wherever possible. Repair scope matches damage survey and FIR.

Sd/- Vijay M

Customer Signature

(Vijay M)

Sd/- Kia Authorised Service Centre - Chennai

Authorised Signatory

(Kia Authorised Service Centre - Chennai)