Sri Balaji Auto Body Works

47, GST Road, Chromepet, Chennai, Tamil Nadu - 600044 | Ph: 044-22765431 | GSTIN: 33BBPSB4412N1Z9

VEHICLE REPAIR ESTIMATION SLIP

Job Card No.: SB-2026-1189	Date: 23 July 2026

CUSTOMER & VEHICLE DETAILS

Customer Name:

Vijay M

Vehicle:

Kia Seltos HTX Plus

Registration No.:

TN-12-AJ-1603

Odometer Reading:

24,680 km

Insurance / Policy No.:

Ganit Motors Insurance / POL-112233

#	Part / Service Description	Work Type	Qty	Source	Amount (Rs.)
1	Front Bumper Assembly (OEM)	Replace	1	OEM	24,500
2	Bonnet / Hood Panel (OEM)	Replace	1	OEM	44,500
3	Front Grille Assembly (OEM)	Replace	1	OEM	13,800
4	Headlight Assembly RH (OEM)	Replace	1	OEM	27,500
5	Front Right Fender	Repair + Paint	1	OEM	15,500
6	Radiator Assembly (OEM)	Replace	1	OEM	22,500
7	Suspension Geometry Check & Wheel Alignment	Service	1	-	4,800
8	Labour - Panel Beating, Denting & Fitment	Labour	1	-	16,500
9	Labour - Painting (2-coat oven finish, 4 panels)	Labour	1	-	12,000

Sub-Total	Rs. 181,600
CGST @ 9%	Rs. 16,344
SGST @ 9%	Rs. 16,344
GRAND TOTAL	**Rs. 214,288**

Note: Heavy front-end structural damage. Full OEM replacement recommended for all impacted assemblies. Estimate valid 15 days; parts subject to availability.

Sd/- Vijay M

Customer Signature

(Vijay M)

Sd/- Sri Balaji Auto Body Works

Authorised Signatory

(Sri Balaji Auto Body Works)