

VEHICLE REPAIR ESTIMATION SLIP

Job Card No.: JC-BLR-2026-4821	Date: 04 June 2026
--------------------------------	--------------------

CUSTOMER & VEHICLE DETAILS

Customer Name:	Rajesh Kumar
Vehicle:	Maruti Suzuki Swift Dzire VXI
Registration No.:	KA-01-MN-2345
Odometer Reading:	41,230 km
Insurance / Policy No.:	Ganit Motors Insurance / POL-784512

#	Part / Service Description	Work Type	Qty	Source	Amount (Rs.)
1	Front Bumper Assembly (OEM)	Replace	1	OEM	8,500
2	Bonnet Panel	Repair + Paint	1	OEM	12,000
3	Front Grille (OEM)	Replace	1	OEM	3,200
4	Headlight Assembly LH (OEM)	Replace	1	OEM	6,800
5	Front Underbody Spoiler	Replace	1	Aftermarket	1,800
6	Labour - Panel Beating & Denting	Labour	1	-	4,500
7	Labour - Painting (2-coat oven finish)	Labour	1	-	3,500

Sub-Total	Rs. 40,300
CGST @ 9%	Rs. 3,627
SGST @ 9%	Rs. 3,627
GRAND TOTAL	Rs. 47,554

Note: Genuine front-end impact damage. All parts OEM wherever possible. Repair matches damage survey.

Sd/- Rajesh Kumar

Customer Signature
(Rajesh Kumar)

Sd/- Vijayanagar Auto Works Pvt. Ltd.

Authorised Signatory
(Vijayanagar Auto Works Pvt. Ltd.)