Sri Balaji Auto Body Works

47, GST Road, Chromepet, Chennai, Tamil Nadu - 600044 | Ph: 044-22765431 | GSTIN: 33BBPSB4412N1Z9

VEHICLE REPAIR ESTIMATION SLIP

Job Card No.: SB-2026-1189	Date: 21 September 2026

CUSTOMER & VEHICLE DETAILS

Customer Name:

Vijay M

Vehicle:

Kia Seltos HTX Plus

Registration No.:

TN-12-AJ-1603

Odometer Reading:

24,680 km

Chassis No. (VIN):

MA2022890123XX

Insurer / Policy No.:

Ganit Motors Insurance Co. Ltd. / POL-112233

Claim No. / Surveyor:

GMI/2026/CHN/041127

#	Part / Service Description	Work Type	Qty	Source	Amount (Rs.)
1	Front Bumper Assembly (OEM)	Replace	1	OEM	34,500
2	Bonnet / Hood Panel (OEM)	Replace	1	OEM	42,000
3	Front Grille Assembly (OEM)	Replace	1	OEM	18,500
4	Headlight Assembly RH (LED Projector, OEM)	Replace	1	OEM	46,000
5	Front Right Fender	Replace	1	OEM	24,500
6	Radiator Assembly (OEM)	Replace	1	OEM	26,500
7	Suspension Geometry Check & Wheel Alignment	Service	1	-	6,500
8	Labour - Panel Beating, Denting & Fitment	Labour	26.0 h	Rs.950/h	24,700
9	Labour - Painting (2-coat oven finish, 7 panels)	Labour	22.0 h	Rs.1050/h	23,100

Sub-Total	Rs. 246,300
CGST @ 9%	Rs. 22,167
SGST @ 9%	Rs. 22,167
GRAND TOTAL	**Rs. 290,634**

Note: Heavy front-end structural damage. Full OEM replacement recommended for all impacted assemblies. Estimate valid 15 days; parts subject to availability.

Sd/- Vijay M

Customer Signature

(Vijay M)

Sd/- B. Prakash

Authorised Signatory

(B. Prakash, Proprietor)

SYNTHETIC SPECIMEN - generated by ClaimIntel for demonstration. Not a genuine commercial document.