Salt Lake Motors - Maruti Suzuki Authorised Service

Sector V, Salt Lake, Kolkata, West Bengal - 700091 | Ph: 033-23578812 | GSTIN: 19AABCS6789K1Z3

VEHICLE REPAIR ESTIMATION SLIP

Job Card No.: SLM-KOL-2026-2201	Date: 20 September 2026

CUSTOMER & VEHICLE DETAILS

Customer Name:

Anjali Gupta

Vehicle:

Maruti Suzuki Alto K10 VXI

Registration No.:

WB-02-PQ-3456

Odometer Reading:

41,860 km

Chassis No. (VIN):

MA2018012345XX

Insurer / Policy No.:

Ganit Motors Insurance Co. Ltd. / POL-667788

#	Part / Service Description	Work Type	Qty	Source	Amount (Rs.)
1	Front Bumper - Repair & Repaint	Repair + Paint	1	OEM	4,200
2	Headlight Housing LH	Replace	1	OEM	3,800
3	Front Number Plate Bracket	Replace	1	OEM	450
4	Labour - Denting & Fitment	Labour	3.0 h	Rs.480/h	1,440
5	Labour - Painting (1 panel)	Labour	2.5 h	Rs.520/h	1,300
6	Consumables (Primer, Masking, Polish)	Material	1	-	800

Sub-Total	Rs. 11,990
CGST @ 9%	Rs. 1,079
SGST @ 9%	Rs. 1,079
GRAND TOTAL	**Rs. 14,148**

Note: Minor front-end scrape against a parking pillar. Cosmetic repair only; no structural damage.

Sd/- Anjali Gupta
Customer Signature
(Anjali Gupta)

Sd/- S. Banerjee
Authorised Signatory
(S. Banerjee, Service Advisor)

SYNTHETIC SPECIMEN - generated by ClaimIntel for demonstration. Not a genuine commercial document.