

Sri Rama Auto Repair Works

Plot 7-B, SIDCO Industrial Area, Ambattur, Chennai - 600098 | Ph: 044-26781234 | GSTIN: 33ZZZR9999X1Z1

VEHICLE REPAIR ESTIMATION SLIP

Job Card No.: JC-CHN-2025-1109	Date: 20 May 2025
--------------------------------	-------------------

CUSTOMER & VEHICLE DETAILS

Customer Name:	Mohammed Faiz
Vehicle:	Toyota Innova Crysta GX 2.4 Diesel
Registration No.:	TN-07-CD-5678
Odometer Reading:	28,540 km
Insurance / Policy No.:	Ganit Motors Insurance / POL-891234

#	Part / Service Description	Work Type	Qty	Source	Amount (Rs.)
1	Left Front Door Skin + Inner Panel (OEM)	Replace	1	OEM	28,000
2	Left Rear Door Assembly (OEM)	Replace	1	OEM	26,500
3	Rear Bumper (OEM)	Replace + Paint	1	OEM	18,000
4	Left Rear Quarter Panel	Repair + Paint	1	OEM	22,000
5	Left ORVM (OEM)	Replace	1	OEM	5,500
6	Running Board LH (OEM)	Replace	1	OEM	8,200
7	Labour - Panel Beating & Alignment	Labour	1	-	12,000
8	Labour - Full Body Paint Blend	Labour	1	-	10,000
9	Consumables (Primer, Polish, Masking)	Material	1	-	4,800

Sub-Total	Rs. 135,000
CGST @ 9%	Rs. 12,150
SGST @ 9%	Rs. 12,150
GRAND TOTAL	Rs. 159,300

Note: WARNING (for demo): This estimate is intentionally inflated by approx 70%+ above OEM rates. Not an empanelled workshop. Refer to fraud screening.

Sd/- Mohammed Faiz

Customer Signature
(Mohammed Faiz)

Sd/- Sri Rama Auto Repair Works

Authorised Signatory
(Sri Rama Auto Repair Works)