

VEHICLE REPAIR ESTIMATION SLIP

Job Card No.: JC-KOC-2026-8812	Date: 13 May 2026
--------------------------------	-------------------

CUSTOMER & VEHICLE DETAILS

Customer Name:	Pooja Nambiar
Vehicle:	Renault Kwid RXT 1.0 SCe
Registration No.:	KL-07-XY-9012
Odometer Reading:	32,480 km
Insurance / Policy No.:	Ganit Motors Insurance / POL-223344

#	Part / Service Description	Work Type	Qty	Source	Amount (Rs.)
1	Rear Bumper Assembly (OEM)	Replace	1	OEM	12,000
2	Trunk Lid / Dicky Door	Repair + Paint	1	OEM	18,000
3	Rear Combination Lamp LH (OEM)	Replace	1	OEM	5,500
4	Rear Combination Lamp RH (OEM)	Replace	1	OEM	5,500
5	Wheel Arch Liner Rear	Repair	1	Aftermarket	3,500
6	Rear Number Plate Bracket	Replace	1	Aftermarket	800
7	Labour - Body Repair	Labour	1	-	8,000
8	Labour - Paint & Polish	Labour	1	-	4,000

Sub-Total	Rs. 57,300
CGST @ 9%	Rs. 5,157
SGST @ 9%	Rs. 5,157
GRAND TOTAL	Rs. 67,614

Note: Rear impact while parked. Scope matches customer complaint. Vehicle brought to Kochi service centre.

Sd/- Pooja Nambiar

Customer Signature
(Pooja Nambiar)

Sd/- Popular Vehicles & Services Pvt. Ltd.

Authorised Signatory
(Popular Vehicles & Services Pvt. Ltd.)