

Head Office: Sector-16, Rohini, Delhi-110089 Office: CSC-7/43, F Block, DDA Market, Sector-16,

Rohini, Delhi

Phone: 999999999

Website: www.autoscanbookvalue.com

TWO WHEELER PRE-INSPECTION REPORT

Request No: KP-N-INDIA-2021-12 Ref. No.: UP11D

Proposer/Customer Name: TEST		Address: H-602 Pan Oasis Apartments Sector 70
Requested Date: 2021-11-06	Requested Time: 03:33	Inspected Date & Time: 2021-11-20 01:03

Requested Date: 2021-11-00	Reque	Requested Time. 03.33	
BODY PARTS	DESCRIPTION	REMARKS	
FR FENDER	Intact	N/A	
FR WHEEL RIM	Intact	N/A	
FR FORK ASSLY	Intact	N/A	
RH FR SHOCKER	Intact	N/A	
HEAD LIGHT	Intact	N/A	
FR CENTER COVER	Intact	N/A	
RH FR PANEL	Intact	N/A	
LH FR PANEL	Intact	N/A	
RH FR INDICATOR LT	Intact	N/A	
LH FR INDICATOR LT	Intact	N/A	
HANDLE BAR	Intact	N/A	
SPEEDOMETER ASSLY	Intact	N/A	
UTILITY BOX	Intact	N/A	
RR BODY	Intact	N/A	
RH RR COWL PANEL	Intact	N/A	
LH RR COWL PANEL	Intact	N/A	
RH RR INDICATOR LT	Intact	N/A	
LH RR INDICATOR LT	Intact	N/A	
TAIL LIGHT ASSLY	Intact	N/A	
LH FOOTREST ASSLY	Intact	N/A	
SEAT	Intact	N/A	
SILENSOR ASSLY	Intact	N/A	
CHASSIS FRAME	Intact	N/A	
FR FOOTBOARD PANEL	Intact	N/A	
RR WHEEL RIM	Intact	N/A	
RH RAER VIEW MIRROR	Intact	N/A	
LH REAR VIEW MIRROR	Intact	N/A	
BATTERY	Intact	N/A	
ENGINE CHAMBER	Intact	N/A	
FUEL TANK	Dented	N/A	

	Inspected Date & Time: 2021-11-20 01:03					
INSURER DETAILS						
INSURER T		THE N	THE NEW INDIA ASSURANCE			
AGENT BRANCH		DELHI	DELHI BRANCH			
AGENT CODENAME		1234				
VEHICLE DETAILS						
VEHICLE NO			UP11D3474			
CHASSIS NO			DSFSDFDSF			
ENGINE NO			SDFDSFDSF			
MAKE		MAHINDRA SCOOTERS				
MODEL		RODEO				
DATE OF REGISTRATION		DSFDSFDSF				
YEAR OF MANUFACTURE			DFDSF			
COLOR		DSFSDF				
ODOMETER			DSFSDF			
FUEL MODE			PETROL			
R.C VERIFIED			DSFDSFDSFSD			
		SIS IMP	PRESSION			
G. Lands Lampine C. Classes and Collection (2020) Goldent Main Goldent		Otto	* (S) Working * (s) was to have fix and corpore * (f) Bill Order Old Proposition (s) (C) (s) (s) (s) (s) (s) (s) (s) (s) (s) (s			
exectly con	NS v 0 Q Search	Giria	as' 104th store in Porur			
Son hoss CA, United States Grouper's Bills William CA, United States William Company and Cartes Explaint TA, United States Explaint TA, Un		DNS Propagatio whateryon reliefs y address and DNS ress the world	processing perform a CNU limiting to which a demonstration councer council period with the control of the contr			
To review the Grant Control of Co		T Depart	104th store in Porur			
Mogazine Dalenina Brasil Dalenina Brasil Serio Comercio di Touten Marese de Brown Spare Gerinare de Brown Spare Gerinare de Brown Spare Gerinare de Brown Spare Gerinare de Brown Spare Monderfield United Gregotom	Cogna Mora Cogna Mora Cogna Mora Establish and Sub-Comma Subset Cogna Subset Cog		Come nint our 1009 1009 1009 1009 1009 1009 1009 100			
Learners Lond (righton Lond (righton Lond (righton Lond)) 1 Sin Face 2 Park Methods (righton Lond) 2 Park Methods (righton Lond) 2 Depart Lond (righton Lond)	mit syntakon mit syntakon mit syntakon mit syntakon mit syntakon mit syntakon	ayaa 🗸 🤍	Parvis, Grass			
■ Laping Generary Unconstruct Enginy □ Bern, Endowshed Indexes and □ State Control of Unconstruct □ State Control of □ State C			F Y (*)			
Continue Navio Atlas Continue Navio Atlas Continue Navior Continue Navior Continue Nation Continue Nation			bell existe with biguers.			

RECOMMENDATION FOR INSURANCE

QC REMARKS

DECLARATION OF OWNERS:

hearby confirm & declare that the above mentioned identification details of my vehicles no UP11D3474 as well as that of damage to this vehicle as noted by the inspecting offical are correct. Nothing has been hidden/Undisclosed.

I further confirm & declare that the Vehicle proposed for insurance after a break in cover has not met with any accident giving rise to any claim by a third party for injury or death caused to any person or damage to any property/insured vehicle during the period following the expiry of a previous insurance, till the moment it is proposed for insurance.

I also agree that damage is mentioned above shall be excluded in the event of any claim being lodged.

Yes

dsfsdfdsfds

For Auto Scan Technical Services



Note: Damages mentioned in this report and/or seen in the photographs are not to be correct for insurance any correction in report will be informed to concerned authorised person within 24 hours.



Head Office: Sector-16, Rohini, Delhi-110089 Office: CSC-7/43, F Block, DDA Market, Sector-16,

Rohini,Delhi

Phone: 9999999999

Website: www.autoscanbookvalue.com