SUMMIT AUTO BODY

2210 Larimer St, Denver, CO 80205 • (303) 555-0199

Repair Estimate

Estimate Date	Estimate #
2026-06-12	EST-44727

Description	Amount
Parts and materials	$13,860.00
Labor	$9,240.00

Total **$28,500.00**