

Feeder 11 North - Defect Survey

Survey date: 03 Jul 2026

Client: Synthetic Utility Co

Site: Feeder 11 North

Defects recorded: 26

Defect register

Ref	Class	Component	Observation	Sheet	
DF-001	Electrical	Conductor	rust scaling	1	
DF-002	Electrical	Conductor	leaning 5 deg	2	
DF-003	Corrosion	Stay wire	rust scaling	2	
DF-004	Structural	Conductor	leaning 5 deg	3	
DF-005	Corrosion	Cross-arm	flashover marks	3	
DF-006	Electrical	Stay wire	rust scaling	4	
DF-007	Vegetation	Conductor	rust scaling	4	
DF-008	Electrical	Pole	flashover marks	5	
DF-009	Corrosion	Stay wire	encroachment 2m	5	
DF-010	Electrical	Conductor	encroachment 2m	6	
DF-011	Corrosion	Insulator	rust scaling	6	
DF-012	Vegetation	Pole	broken strand	7	
DF-013	Electrical	Conductor	flashover marks	7	
DF-014	Structural	Insulator	rust scaling	8	
DF-015	Electrical	Conductor	rust scaling	8	
DF-016	Vegetation	Stay wire	rust scaling	9	
DF-017	Electrical	Cross-arm	leaning 5 deg	9	
DF-018	Structural	Conductor	broken strand	10	
DF-019	Electrical	Cross-arm	rust scaling	10	
DF-020	Electrical	Pole	broken strand	11	
DF-021	Vegetation	Pole	flashover marks	11	
DF-022	Corrosion	Insulator	hairline crack	12	
DF-023	Structural	Cross-arm	rust scaling	12	

Ref	Class	Component	Observation	Sheet	
DF-024	Corrosion	Insulator	rust scaling	13	
DF-025	Electrical	Stay wire	rust scaling	13	
DF-026	Electrical	Stay wire	leaning 5 deg	14	