

Feeder 12 East - Defect Survey

Survey date: 03 Jul 2026

Client: Synthetic Utility Co

Site: Feeder 11 North

Defects recorded: 9

Defect register

Ref	Class	Component	Observation	Sheet	
DF-001	Electrical	Insulator	hairline crack	1	
DF-002	Structural	Conductor	hairline crack	2	
DF-003	Vegetation	Conductor	hairline crack	2	
DF-004	Structural	Insulator	leaning 5 deg	3	
DF-005	Corrosion	Insulator	flashover marks	3	
DF-006	Corrosion	Insulator	leaning 5 deg	4	
DF-007	Vegetation	Stay wire	leaning 5 deg	4	
DF-008	Structural	Pole	flashover marks	5	
DF-009	Vegetation	Pole	encroachment 2m	5	