

Feeder 13 South - Defect Survey

Survey date: 03 Jul 2026

Client: Synthetic Utility Co

Site: Feeder 11 North

Defects recorded: 7

Defect register

Ref	Category	Component	Observation	Sheet	
DF-001	Structural	Conductor	broken strand	1	
DF-002	Electrical	Stay wire	hairline crack	2	
DF-003	Corrosion	Conductor	leaning 5 deg	2	
DF-004	Electrical	Conductor	leaning 5 deg	3	
DF-005	Vegetation	Conductor	encroachment 2m	3	
DF-006	Vegetation	Pole	leaning 5 deg	4	
DF-007	Electrical	Conductor	rust scaling	4	