

Feeder 14 West - Defect Survey

Survey date: 03 Jul 2026

Client: Synthetic Utility Co

Site: Feeder 11 North

Defects recorded: 12

Defect register

Ref	Class	Component	Observation	Sheet	
DF-001	Vegetation	Conductor	broken strand	1	
DF-002	Structural	Stay wire	leaning 5 deg	2	
DF-003	Electrical	Conductor	rust scaling	2	
DF-004				3	
DF-005	Electrical	Pole	leaning 5 deg	3	
DF-006	Vegetation	Pole	encroachment 2m	4	
DF-007	Vegetation	Conductor	encroachment 2m	4	
DF-008				5	
DF-009	Vegetation	Conductor	flashover marks	5	
DF-010	Electrical	Insulator	leaning 5 deg	6	
DF-011	Electrical	Stay wire	broken strand	6	
DF-012				7	