

Heat Pump Health Check Report

Your personalised assessment from Integrity Heat Pumps

Your Details

Name	Wajahat Hafeez
Postcode	12312313
Report Date	7th April 2026
Reference	REF-25234
Property Type	terraced
Bedrooms	3
Home Insulation	poor
Heat Pump Make / Model	YVL125A35CG

Overall Health Check Rating



RED — System requires immediate attention

Significant issues detected with airflow and outdoor unit condition.

Note: This free assessment is based on your photographs and questionnaire answers. It is not a substitute for an in-person inspection.

What We Found — Quick Checklist

Here is a summary of the key checks we carried out based on your photos and answers:

Check Item	Status
Outdoor unit airflow	⚠️ Action Needed
Outdoor unit cycling	⚠️ Issue Found
Ice buildup / defrost	✅ OK
Controller settings	✅ OK
Hot water tank	✅ OK
Pipework	⚠️ Issue Found
Radiators & TRVs	✅ OK

✅ *OK* | ⚠️ *Action Needed* | ⚠️ *Issue Found*

The 3 Most Common Efficiency Killers

Based on your answers, here is how your system performs against the three issues we see most often:

 **Efficiency Killer #1 — The On/Off Mistake**

The biggest mistake hardworking families make is switching the heating off at night. Don't do it. A heat pump isn't a sprinter; it's a marathon runner. It's designed to hum along at a steady 18°C–21°C all day and night. Keep it on, let it run low and slow.

 **Efficiency Killer #2 — Don't "Choke" Your Radiators**

You might think you're saving electricity by turning off radiators in the spare room, but you're actually choking the system. Your heat pump needs the heating system water to flow freely, to work properly. Shutting radiator valves (TRVs), forces the pump to "short-cycle"—turning on and off every few minutes like a car stuck in traffic. This wears out the heat pump and sends your electric meter spinning.
Keep those radiator valves wide open for a warm house and fair bills.

 **Efficiency Killer #3 — Hot Water Tank Immersion Overuse**

Hidden inside your water tank is a backup immersion heater. It's just like a power-hungry electric kettle. Your heat pump is perfectly capable of heating your bath water. The only time the immersion should kick in is once a week to kill off any legionella bugs. If yours is running every day, your hot water is more expensive than it needs to be. **Check your settings and make sure the pump is in charge.**

Your Simple Action List

These are the quick wins we recommend you try first. They cost nothing and can make a noticeable difference to your comfort and bills:

- Increase clearance around the outdoor unit to at least 300mm on all sides, especially the fan outlet, by modifying or removing the surrounding structure.
- Verify hot water cylinder temperature settings to ensure it's not set excessively high and that an immersion heater (if present) is not activating unnecessarily.
- Check the outdoor unit — inspect the rear of the unit for any ice build-up. Some frosting is normal in cold weather, but a thick layer of ice that doesn't clear within an hour or two could indicate a defrost fault.
- Schedule a professional system health check and commissioning review by an MCS-certified engineer to ensure optimal performance and identify any minor inefficiencies.

- Check your hot water cylinder settings — if your 'Boost' or immersion heater is running daily, consider reducing the frequency or temperature to the minimum safe level (60°C).

Want to Go Deeper? Your Next Steps

This free report focuses on the most impactful quick wins. If you'd like a more detailed look at your specific heat pump setup — or you're still not getting the warmth or bills you expect — here's how we can help further:

	What You Get	Price
✔	FREE Health Check — you already have this!	FREE
↑	Performance Optimisation Report — a deeper dive into your specific setup, with tailored recommendations to cut your bills and improve comfort.	£39
🏠	Home Visit & System MOT — a qualified engineer visits, checks everything in person, and follows up with a written action plan.	£350

To find out more or to book your **Performance Optimisation Report**, visit us at www.IntegrityHeatPumps.co.uk or reply to the email this report arrived in.

Disclaimer: This report is based solely on the photographs and questionnaire responses provided by the customer. Integrity Heat Pumps accepts no liability for actions taken on the basis of this report without a full in-person inspection.
All assessments are indicative only.

Integrity Heat Pumps | www.IntegrityHeatPumps.co.uk | This report is confidential to the named recipient.