

SECTION 10: LOCKOUT/TAGOUT (LOTO) PROCEDURES SOP

Purpose: Protect personnel from unexpected startup or release of hazardous energy during maintenance, servicing, or inspection of boiler systems.

Procedures:

Notify all affected personnel of maintenance and LOTO intent.

Shut down system and isolate all energy sources (electrical, pneumatic, hydraulic, thermal).

Apply lockout devices and clearly labeled tags on all isolation points.

Release stored energy from lines, valves, and pressure vessels.

Attempt system restart to verify zero energy state.

Complete logbook entry and secure keys to lockout devices.

Only authorized personnel may remove locks/tags after task completion.

Notes:

Train all authorized employees annually.

Maintain written LOTO program per OSHA 1910.147.