

 2. Critical Measurements & Test Points

Parameter	Tool/Method	Expected Range
Motor Amperage Draw	Clamp meter	Within 90–100% of FLA
Vibration Levels	Vibration analyzer	<0.2 in/sec RMS (non-critical)
Static Pressure (duct)	Manometer	According to design spec
Fan RPM	Tachometer	Rated RPM $\pm 10\%$
Voltage Supply	Multimeter	120/208/240/480V $\pm 5\%$

 3. Emergency Conditions

Event	Immediate Action
Fan blade separation	Shut down system, isolate circuit
Electrical burning smell	Disconnect power, inspect motor
High vibration alert	Stop fan, perform balance check
Continuous overload trips	Evaluate motor load and voltage