

2. Test Points & Reference Ranges

Test Point	Method	Ideal Value or Range
Basin Water Temp	Thermometer or sensor	80–95°F
Condenser Water Delta-T	Inlet vs outlet temp	8–12°F
Fan Motor Amps	Clamp meter	Per manufacturer FLA rating
pH (if treated)	Water test strips or probe	6.8–7.8
Total Dissolved Solids	Conductivity meter	< 2000 ppm (based on system)

3. Emergency Conditions

Event	Required Response
Fan Seizes or Trips	Lockout power, inspect motor & bearings
Overflowing Basin	Verify float valve and drain clearance
Biological Outbreak	Shut system, shock treatment, flush
Ice Formation in Cold Weather	Use basin heater or bypass valve