


SMART-TECH ELECTRO-INDUSTRIAL


GEN. CONTRACTOR • DESIGNERS • PLANNERS • CONSULTANTS
• POWER SUBSTATION ENGINEERS • SUPPLIER / IMPORTER •





		Reference No.	2023-0022
Customer	TERUMO PHILIPPINES CORPORATION	Report No.	01
Address	124 East Main Avenue, Laguna Techno park Inc. Biñan, Laguna	Inspection Dates	Remarks
Location	Plant 1, Ground Floor, Electrical Room-3		
Equipment ID	MSB-3		
Component	300AT, 3P, CB.no.5		





Thermograph

Reference

Data

Subjects Measured Temperature			Amb.	ΔΤ	Е		
Hotspot	Description	Temp. ℃	T ℃	Temp Diff	(Emissivity)	Category of Anomaly	
Area 1	Line side	45.1 ℃	28.5 ℃	16.6 ℃	0.95	2nd STAGE	INTERMEDIATE
Area 2	Load side	43.8 °C	28.5 ℃	15.3 °C	0.95	2nd STAGE	INTERMEDIATE

Subject	AT		Type of	Brand		Load Current			
Description	Rating	Pole	Breaker	Catalog No.	Size of Wire	ØA	ØB	ØC	Remarks
Branch CB. 5	300	3	MCCB	Mitsubishi	Busbar Conn.	206A	249A	210A	Hot-spot

Evaluation

Elevated temperature was detected and the problem persists. Though, the situatuon is still manageable and allowable.

Recommendation

1. For close monitoring.

Corrective Action Taken

Date

Done by

1. Check/clean terminals & Retighten all bolted connections.

December 28, 2023 SMART-TECH

Undertaken By SMART-TECH

Date
Approved by:

Customer Representative

December 26, 2023

Inspected/Evaluated by: Reviewed by:

Karl Jason V. Nullas
Asst. Thermographer

Karl Jason V. Nullas
Asst. Thermographer

Stephen F. Collao, P.E.E. Certified Thermographer - I

Engr. Jovin P. Dumilig