Dealership Progress Report

XPENG Service Center Aix-en-Provence x Deffeuille

ZONE PERFORMANCE / South-East / 25 October 2026

PROGRESS	COMPLETED	REMAINING	CAMPAIGNS BELOW TARGET
63.2%	**36**	**21**	**7**
36 completed of 57	records closed	records to complete	of 13 campaigns

Current status

Status	Records	Share of dealership total
Finished	36	63.2%
To be finished	21	36.8%

Where to investigate first

Campaign hotspot: 26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection has 11 open of 11 records.

Vehicle signal: G9_2024 AWD Performance has 9 open records.

21 open campaign records cover 20 distinct VINs.

These are observed workload patterns, not proof that this dealership caused the issue.

Data gap: 21 of 21 open cases lack a job-order number, and 21 lack a completion date. Check source-system data before attributing responsibility or estimating delay.

Campaigns driving open workload

Campaign case counts, completion and open workload for this dealership.

Campaign code / name	Total	Completed	Open	Progress	Extra to 85%
26ODBXI1-1 G9 Wiring Harness Body Deputy Inspection	11	0	11	0.0%	10
25OBTDN1 New G6 Cup Holder Replacement(Impressive Gray)	4	1	3	25.0%	3
25OTCGN2-1 G9 Electric tow hook label	6	3	3	50.0%	3
25OBTDN1-1 New G6 Cup Holder Replacement(Dark Gray)	4	3	1	75.0%	1
25OXDCP1 SC–G6 Repair the 12V Battery negative ground point	3	2	1	66.7%	1
26OCGQI1-2 P7plus - Height Sensor Inspection	1	0	1	0.0%	1
26OMBSI1-EU P7 plus Front Exterior Door Handle Replacement	1	0	1	0.0%	1

By campaign type

Segment	Total	Completed	Open	Completion
CIC(Customer Incoming service Campaign)	13	0	13	0.0%
PSC(Pre-delivery Service Campaign)	26	18	8	69.2%

Vehicle and record detail

Use vehicle and tier concentrations to narrow a technical review; confirm against campaign eligibility and workshop evidence.

By vehicle model

Segment	Total	Completed	Open	Completion
G9_2024 AWD Performance	10	1	9	10.0%
New G6 RWD Long Range	10	6	4	60.0%
New G9 AWD Performance	8	5	3	62.5%
G9_2024 RWD Long Range	2	0	2	0.0%
P7+ RWD Long Range	2	0	2	0.0%
G6 AWD Performance	3	2	1	66.7%

By campaign tier

Segment	Total	Completed	Open	Completion
General	37	17	20	45.9%
Important	18	17	1	94.4%

Campaign-by-campaign progress

Use this table to track completion and remaining workload.

Campaign code	Campaign	Total	Completed	Remaining	Progress
25OYKBN1	New G9/New G6 - UWB Smart Key Update	15	15	0	100.0%
26ODBXI1-1	G9 Wiring Harness Body Deputy Inspection	11	0	11	0.0%
25OTCGN2	G6 Electric tow hook label	8	8	0	100.0%
25OTCGN2-1	G9 Electric tow hook label	6	3	3	50.0%
25OBTDN1	New G6 Cup Holder Replacement(Impressive Gray)	4	1	3	25.0%
25OBTDN1-1	New G6 Cup Holder Replacement(Dark Gray)	4	3	1	75.0%
25OXDCP1	SC–G6 Repair the 12V Battery negative ground point	3	2	1	66.7%
24OXDYP1	G6-Reduce the concentration of cleaning fluid	1	1	0	100.0%
25WDCFN1	SC–G6 HV battery replacement	1	1	0	100.0%
26OCGQI1-2	P7plus - Height Sensor Inspection	1	0	1	0.0%
26OMBSI1-EU	P7 plus Front Exterior Door Handle Replacement	1	0	1	0.0%
EsimTBOX-G6-1	G6-Esim-TBOX delayed claiming	1	1	0	100.0%
EsimTBOX-G9-1	G9-Esim-TBOX delayed claiming	1	1	0	100.0%