Dealership Progress Report

XPENG Service Center Le Cannet x Mozart Autos

ZONE PERFORMANCE / South-East / 25 October 2026

PROGRESS	COMPLETED	REMAINING	CAMPAIGNS BELOW TARGET
69.6%	**87**	**38**	**8**
87 completed of 125	records closed	records to complete	of 15 campaigns

Current status

Status	Records	Share of dealership total
Finished	87	69.6%
To be finished	38	30.4%

Where to investigate first

Campaign hotspot: 26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection has 25 open of 30 records.

Vehicle signal: G9_2024 AWD Performance has 15 open records.

38 open campaign records cover 35 distinct VINs.

These are observed workload patterns, not proof that this dealership caused the issue.

Data gap: 38 of 38 open cases lack a job-order number, and 38 lack a completion date. Check source-system data before attributing responsibility or estimating delay.

Campaigns driving open workload

Campaign case counts, completion and open workload for this dealership.

Campaign code / name	Total	Completed	Open	Progress	Extra to 85%
26ODBXI1-1 G9 Wiring Harness Body Deputy Inspection	30	5	25	16.7%	21
25OTCGN2-1 G9 Electric tow hook label	4	1	3	25.0%	3
25OBTDN1 New G6 Cup Holder Replacement(Impressive Gray)	7	5	2	71.4%	1
25OBTDN1-1 New G6 Cup Holder Replacement(Dark Gray)	11	9	2	81.8%	1
24OXDYP1 G6-Reduce the concentration of cleaning fluid	11	10	1	90.9%	0
26OCGQI1-2 P7plus - Height Sensor Inspection	1	0	1	0.0%	1
26OMBSI1-EU P7 plus Front Exterior Door Handle Replacement	1	0	1	0.0%	1
EsimTBOX-G6-1 G6-Esim-TBOX delayed claiming	1	0	1	0.0%	1
EsimTBOX-G9-1 G9-Esim-TBOX delayed claiming	2	1	1	50.0%	1
G9MY3231 SC-G9 Pasting the vehicle nameplate	8	7	1	87.5%	0

By campaign type

Segment	Total	Completed	Open	Completion
CIC(Customer Incoming service Campaign)	33	6	27	18.2%
PSC(Pre-delivery Service Campaign)	65	57	8	87.7%
SSC(Special Service Campaign)	27	24	3	88.9%

Vehicle and record detail

Use vehicle and tier concentrations to narrow a technical review; confirm against campaign eligibility and workshop evidence.

By vehicle model

Segment	Total	Completed	Open	Completion
G9_2024 AWD Performance	20	5	15	25.0%
G9_2024 RWD Long Range	16	5	11	31.2%
New G6 RWD Long Range	33	29	4	87.9%
New G9 AWD Performance	4	1	3	25.0%
G6 RWD Long Range	22	20	2	90.9%
P7+ RWD Long Range	2	0	2	0.0%
G9 AWD Performance	5	4	1	80.0%

By campaign tier

Segment	Total	Completed	Open	Completion
General	66	30	36	45.5%
Important	48	47	1	97.9%
Tier not recorded	11	10	1	90.9%

Campaign-by-campaign progress

Use this table to track completion and remaining workload.

Campaign code	Campaign	Total	Completed	Remaining	Progress
26ODBXI1-1	G9 Wiring Harness Body Deputy Inspection	30	5	25	16.7%
25OXDCP1	SC–G6 Repair the 12V Battery negative ground point	21	21	0	100.0%
25OYKBN1	New G9/New G6 - UWB Smart Key Update	16	16	0	100.0%
24OXDYP1	G6-Reduce the concentration of cleaning fluid	11	10	1	90.9%
25OBTDN1-1	New G6 Cup Holder Replacement(Dark Gray)	11	9	2	81.8%
25OTCGN2	G6 Electric tow hook label	9	9	0	100.0%
G9MY3231	SC-G9 Pasting the vehicle nameplate	8	7	1	87.5%
25OBTDN1	New G6 Cup Holder Replacement(Impressive Gray)	7	5	2	71.4%
25OTCGN2-1	G9 Electric tow hook label	4	1	3	25.0%
24OZYPN1	G6-Driver/Front passenger seat cushion improvement	2	2	0	100.0%
EsimTBOX-G9-1	G9-Esim-TBOX delayed claiming	2	1	1	50.0%
24ODHBN1-04	Corrosion prevention of battery pack bottom-G9-2	1	1	0	100.0%
26OCGQI1-2	P7plus - Height Sensor Inspection	1	0	1	0.0%
26OMBSI1-EU	P7 plus Front Exterior Door Handle Replacement	1	0	1	0.0%
EsimTBOX-G6-1	G6-Esim-TBOX delayed claiming	1	0	1	0.0%