Dealership Progress Report

XPENG Service Center Montpellier x GRIM

ZONE PERFORMANCE / South-East / 25 October 2026

PROGRESS	COMPLETED	REMAINING	CAMPAIGNS BELOW TARGET
50.0%	**35**	**35**	**8**
35 completed of 70	records closed	records to complete	of 10 campaigns

Current status

Status	Records	Share of dealership total
Finished	35	50.0%
To be finished	35	50.0%

Campaigns below 85% target

Campaign code	Campaign	Total	Completed	Remaining	Progress	Extra to 85%
26ODBXI1-1	G9 Wiring Harness Body Deputy Inspection	15	0	15	0.0%	13
25OYKBN1	New G9/New G6 - UWB Smart Key Update	18	12	6	66.7%	4
25OTCGN2	G6 Electric tow hook label	15	11	4	73.3%	2
25OBTDN1-1	New G6 Cup Holder Replacement(Dark Gray)	3	0	3	0.0%	3
25OBTDN1	New G6 Cup Holder Replacement(Impressive Gray)	6	3	3	50.0%	3
25OTCGN2-1	G9 Electric tow hook label	4	2	2	50.0%	2
26OMBSI1-EU	P7 plus Front Exterior Door Handle Replacement	1	0	1	0.0%	1
26OCGQI1-2	P7plus - Height Sensor Inspection	1	0	1	0.0%	1

Campaign-by-campaign progress

Use this table to track completion and remaining workload.

Campaign code	Campaign	Total	Completed	Remaining	Progress
25OYKBN1	New G9/New G6 - UWB Smart Key Update	18	12	6	66.7%
25OTCGN2	G6 Electric tow hook label	15	11	4	73.3%
26ODBXI1-1	G9 Wiring Harness Body Deputy Inspection	15	0	15	0.0%
25OBTDN1	New G6 Cup Holder Replacement(Impressive Gray)	6	3	3	50.0%
25OXDCP1	SC–G6 Repair the 12V Battery negative ground point	6	6	0	100.0%
25OTCGN2-1	G9 Electric tow hook label	4	2	2	50.0%
25OBTDN1-1	New G6 Cup Holder Replacement(Dark Gray)	3	0	3	0.0%
26OCGQI1-2	P7plus - Height Sensor Inspection	1	0	1	0.0%
26OMBSI1-EU	P7 plus Front Exterior Door Handle Replacement	1	0	1	0.0%
EsimTBOX-G6-1	G6-Esim-TBOX delayed claiming	1	1	0	100.0%