Dealership Progress Report

XPENG Service RVO Clermont-Ferrand France

ZONE PERFORMANCE / South-East / 25 October 2026

PROGRESS	COMPLETED	REMAINING	CAMPAIGNS BELOW TARGET
67.6%	**23**	**11**	**6**
23 completed of 34	records closed	records to complete	of 11 campaigns

Current status

Status	Records	Share of dealership total
Finished	23	67.6%
To be finished	11	32.4%

Where to investigate first

Campaign hotspot: 26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection has 4 open of 6 records.

Vehicle signal: G9_2024 AWD Performance has 5 open records.

11 open campaign records cover 9 distinct VINs.

These are observed workload patterns, not proof that this dealership caused the issue.

Data gap: 11 of 11 open cases lack a job-order number, and 11 lack a completion date. Check source-system data before attributing responsibility or estimating delay.

Campaigns driving open workload

Campaign case counts, completion and open workload for this dealership.

Campaign code / name	Total	Completed	Open	Progress	Extra to 85%
26ODBXI1-1 G9 Wiring Harness Body Deputy Inspection	6	2	4	33.3%	4
25OBTDN1 New G6 Cup Holder Replacement(Impressive Gray)	3	1	2	33.3%	2
25WDCFN1-3 SC – G9 HV battery replacement	2	0	2	0.0%	2
25OTCGN2-1 G9 Electric tow hook label	1	0	1	0.0%	1
26OCGQI1-2 P7plus - Height Sensor Inspection	1	0	1	0.0%	1
26OMBSI1-EU P7 plus Front Exterior Door Handle Replacement	1	0	1	0.0%	1

By campaign type

Segment	Total	Completed	Open	Completion
CIC(Customer Incoming service Campaign)	8	2	6	25.0%
PSC(Pre-delivery Service Campaign)	16	13	3	81.2%
CNC(Customer Notification service Campaign)	2	0	2	0.0%

Vehicle and record detail

Use vehicle and tier concentrations to narrow a technical review; confirm against campaign eligibility and workshop evidence.

By vehicle model

Segment	Total	Completed	Open	Completion
G9_2024 AWD Performance	6	1	5	16.7%
New G6 RWD Long Range	6	4	2	66.7%
P7+ RWD Long Range	2	0	2	0.0%
G9_2024 RWD Long Range	2	1	1	50.0%
New G9 AWD Performance	1	0	1	0.0%

By campaign tier

Segment	Total	Completed	Open	Completion
General	20	11	9	55.0%
Very Important	2	0	2	0.0%

Campaign-by-campaign progress

Use this table to track completion and remaining workload.

Campaign code	Campaign	Total	Completed	Remaining	Progress
25OYKBN1	New G9/New G6 - UWB Smart Key Update	8	8	0	100.0%
26ODBXI1-1	G9 Wiring Harness Body Deputy Inspection	6	2	4	33.3%
25OTCGN2	G6 Electric tow hook label	5	5	0	100.0%
25OBTDN1	New G6 Cup Holder Replacement(Impressive Gray)	3	1	2	33.3%
25OBTDN1-1	New G6 Cup Holder Replacement(Dark Gray)	3	3	0	100.0%
25OXDCP1	SC–G6 Repair the 12V Battery negative ground point	3	3	0	100.0%
25WDCFN1-3	SC – G9 HV battery replacement	2	0	2	0.0%
24OXDYP1	G6-Reduce the concentration of cleaning fluid	1	1	0	100.0%
25OTCGN2-1	G9 Electric tow hook label	1	0	1	0.0%
26OCGQI1-2	P7plus - Height Sensor Inspection	1	0	1	0.0%
26OMBSI1-EU	P7 plus Front Exterior Door Handle Replacement	1	0	1	0.0%