Global Service Campaign Report — South-East

Executive summary and review priorities

ZONE PERFORMANCE / South-East / 25 October 2026

OVERALL PROGRESS	REMAINING WORKLOAD	DEALERSHIPS BELOW TARGET	CAMPAIGNS BELOW TARGET
68.4%	**211**	**11**	**8**
457 completed out of 668	records still to complete	of 13 dealerships	of 16 campaigns

Meeting takeaways

Overall: 457 of 668 records completed (68.4%); 211 remain. Reference target: 85%.

Priority dealership: XPENG Service Center Le Cannet x Mozart Autos has 38 remaining at 69.6% progress.

Largest campaign workload: G9 Wiring Harness Body Deputy Inspection has 95 remaining at 10.4% progress.

Workload by status

Status	Records	Share of total
Finished	457	68.4%
To be finished	211	31.6%

Dealership progress

Progress bars are color-coded against the 85% reference target.

Dealership	Total	Completed	Remaining	Progress
XPENG Service Center Le Cannet x Mozart Autos	125	87	38	69.6%
XPENG Service Center Fréjus Mapauto	93	80	13	86.0%
XPENG Service Center Montpellier x GRIM	70	35	35	50.0%
XPENG Service Center Marseille x Parascandola	60	39	21	65.0%
XPENG Service Center Aix-en-Provence x Deffeuille	57	36	21	63.2%
XPENG Service Center Nice x Mozart Autos	54	47	7	87.0%
XPENG Service Center Béziers x GRIM	39	27	12	69.2%
XPENG Service Center Nîmes x Grim	39	31	8	79.5%
XPENG Service Center Bastia x Groupe SIA	33	26	7	78.8%
XPENG Service Center Rodez Negrier	31	21	10	67.7%
XPENG Service Center Perpignan x LG	29	15	14	51.7%
XPENG Service Center Bandol x Etoile 83	28	8	20	28.6%
XPENG Service Center Toulon Est x Etoile 83	10	5	5	50.0%

Zone total: 457 completed of 668 records (68.4%). Records without a dealership: 0.

Dealerships to review

11 of 13 dealerships are below the 85% target. Highest workloads are listed first.

Dealership	Total	Completed	Remaining	Progress	Extra to 85%
XPENG Service Center Le Cannet x Mozart Autos	125	87	38	69.6%	20
XPENG Service Center Montpellier x GRIM	70	35	35	50.0%	25
XPENG Service Center Aix-en-Provence x Deffeuille	57	36	21	63.2%	13
XPENG Service Center Marseille x Parascandola	60	39	21	65.0%	12
XPENG Service Center Bandol x Etoile 83	28	8	20	28.6%	16
XPENG Service Center Perpignan x LG	29	15	14	51.7%	10
XPENG Service Center Béziers x GRIM	39	27	12	69.2%	7
XPENG Service Center Rodez Negrier	31	21	10	67.7%	6
XPENG Service Center Nîmes x Grim	39	31	8	79.5%	3
XPENG Service Center Bastia x Groupe SIA	33	26	7	78.8%	3
XPENG Service Center Toulon Est x Etoile 83	10	5	5	50.0%	4

Campaigns to review

Campaigns below target, ranked by remaining records.

Campaign code	Campaign	Total	Completed	Remaining	Progress	Extra to 85%
26ODBXI1-1	G9 Wiring Harness Body Deputy Inspection	106	11	95	10.4%	80
25OBTDN1-1	New G6 Cup Holder Replacement(Dark Gray)	66	47	19	71.2%	10
25OTCGN2-1	G9 Electric tow hook label	51	33	18	64.7%	11
25OBTDN1	New G6 Cup Holder Replacement(Impressive Gray)	55	38	17	69.1%	9
25OTCGN2	G6 Electric tow hook label	83	68	15	81.9%	3
26OMBSI1-EU	P7 plus Front Exterior Door Handle Replacement	14	2	12	14.3%	10
26OCGQI1-2	P7plus - Height Sensor Inspection	12	4	8	33.3%	7
EsimTBOX-G9-1	G9-Esim-TBOX delayed claiming	3	2	1	66.7%	1

Full campaign progress

All 16 campaigns in the South-East zone.

Campaign code	Campaign	Total	Completed	Remaining	Progress
25OYKBN1	New G9/New G6 - UWB Smart Key Update	160	138	22	86.2%
26ODBXI1-1	G9 Wiring Harness Body Deputy Inspection	106	11	95	10.4%
25OTCGN2	G6 Electric tow hook label	83	68	15	81.9%
25OXDCP1	SC–G6 Repair the 12V Battery negative ground point	74	73	1	98.6%
25OBTDN1-1	New G6 Cup Holder Replacement(Dark Gray)	66	47	19	71.2%
25OBTDN1	New G6 Cup Holder Replacement(Impressive Gray)	55	38	17	69.1%
25OTCGN2-1	G9 Electric tow hook label	51	33	18	64.7%
24OXDYP1	G6-Reduce the concentration of cleaning fluid	20	19	1	95.0%
26OMBSI1-EU	P7 plus Front Exterior Door Handle Replacement	14	2	12	14.3%
26OCGQI1-2	P7plus - Height Sensor Inspection	12	4	8	33.3%
G9MY3231	SC-G9 Pasting the vehicle nameplate	11	10	1	90.9%
EsimTBOX-G6-1	G6-Esim-TBOX delayed claiming	7	6	1	85.7%
25WDCFN1	SC–G6 HV battery replacement	3	3	0	100.0%
EsimTBOX-G9-1	G9-Esim-TBOX delayed claiming	3	2	1	66.7%
24OZYPN1	G6-Driver/Front passenger seat cushion improvement	2	2	0	100.0%
24ODHBN1-04	Corrosion prevention of battery pack bottom-G9-2	1	1	0	100.0%