Global Service Campaign Report — South-East

Executive summary and review priorities

ZONE PERFORMANCE / South-East / 25 October 2026

OVERALL PROGRESS	REMAINING WORKLOAD	DEALERSHIPS BELOW TARGET	CAMPAIGNS BELOW TARGET
68.4%	**211**	**11**	**8**
457 completed out of 668	records still to complete	of 13 dealerships	of 16 campaigns

Meeting takeaways

Overall: 457 of 668 records completed (68.4%); 211 remain. Reference target: 85%.

Priority dealership: XPENG Service Center Le Cannet x Mozart Autos has 38 remaining at 69.6% progress.

Largest campaign workload: G9 Wiring Harness Body Deputy Inspection has 95 remaining at 10.4% progress.

Campaign type signal: CIC(Customer Incoming service Campaign) has 115 open records.

Vehicle signal: G9_2024 AWD Performance has 74 open records.

These are workload concentrations to investigate, not proof of dealership fault.

Workload by status

Status	Records	Share of total
Finished	457	68.4%
To be finished	211	31.6%

Dealership progress

Progress bars are color-coded against the 85% reference target.

Dealership	Total	Completed	Open	Completion	Zone open share
XPENG Service Center Le Cannet x Mozart Autos	125	87	38	69.6%	18.0%
XPENG Service Center Fréjus Mapauto	93	80	13	86.0%	6.2%
XPENG Service Center Montpellier x GRIM	70	35	35	50.0%	16.6%
XPENG Service Center Marseille x Parascandola	60	39	21	65.0%	10.0%
XPENG Service Center Aix-en-Provence x Deffeuille	57	36	21	63.2%	10.0%
XPENG Service Center Nice x Mozart Autos	54	47	7	87.0%	3.3%
XPENG Service Center Béziers x GRIM	39	27	12	69.2%	5.7%
XPENG Service Center Nîmes x Grim	39	31	8	79.5%	3.8%
XPENG Service Center Bastia x Groupe SIA	33	26	7	78.8%	3.3%
XPENG Service Center Rodez Negrier	31	21	10	67.7%	4.7%
XPENG Service Center Perpignan x LG	29	15	14	51.7%	6.6%
XPENG Service Center Bandol x Etoile 83	28	8	20	28.6%	9.5%
XPENG Service Center Toulon Est x Etoile 83	10	5	5	50.0%	2.4%

Zone total: 457 completed of 668 records (68.4%). Records without a dealership: 0.

Dealerships to review

11 of 13 dealerships are below the 85% target. Highest workloads are listed first.

Dealership	Total	Completed	Open	Completion	Extra to 85%	Zone open sh
XPENG Service Center Le Cannet x Mozart Autos	125	87	38	69.6%	20	18.0%
XPENG Service Center Montpellier x GRIM	70	35	35	50.0%	25	16.6%
XPENG Service Center Aix-en-Provence x Deffeuille	57	36	21	63.2%	13	10.0%
XPENG Service Center Marseille x Parascandola	60	39	21	65.0%	12	10.0%
XPENG Service Center Bandol x Etoile 83	28	8	20	28.6%	16	9.5%
XPENG Service Center Perpignan x LG	29	15	14	51.7%	10	6.6%
XPENG Service Center Béziers x GRIM	39	27	12	69.2%	7	5.7%
XPENG Service Center Rodez Negrier	31	21	10	67.7%	6	4.7%
XPENG Service Center Nîmes x Grim	39	31	8	79.5%	3	3.8%
XPENG Service Center Bastia x Groupe SIA	33	26	7	78.8%	3	3.3%
XPENG Service Center Toulon Est x Etoile 83	10	5	5	50.0%	4	2.4%

Campaigns to review

Campaigns below target, ranked by remaining records.

Campaign code	Campaign	Total	Completed	Remaining	Progress	Extra to 85%
26ODBXI1-1	G9 Wiring Harness Body Deputy Inspection	106	11	95	10.4%	80
25OBTDN1-1	New G6 Cup Holder Replacement(Dark Gray)	66	47	19	71.2%	10
25OTCGN2-1	G9 Electric tow hook label	51	33	18	64.7%	11
25OBTDN1	New G6 Cup Holder Replacement(Impressive Gray)	55	38	17	69.1%	9
25OTCGN2	G6 Electric tow hook label	83	68	15	81.9%	3
26OMBSI1-EU	P7 plus Front Exterior Door Handle Replacement	14	2	12	14.3%	10
26OCGQI1-2	P7plus - Height Sensor Inspection	12	4	8	33.3%	7
EsimTBOX-G9-1	G9-Esim-TBOX delayed claiming	3	2	1	66.7%	1

Campaign and process drivers

Open cases grouped by campaign and campaign type. Completion bars show the share of records already finished.

Campaign code / name	Total	Completed	Open	Progress	Extra to 85%
26ODBXI1-1 G9 Wiring Harness Body Deputy Inspection	106	11	95	10.4%	80
25OYKBN1 New G9/New G6 - UWB Smart Key Update	160	138	22	86.2%	0
25OBTDN1-1 New G6 Cup Holder Replacement(Dark Gray)	66	47	19	71.2%	10
25OTCGN2-1 G9 Electric tow hook label	51	33	18	64.7%	11
25OBTDN1 New G6 Cup Holder Replacement(Impressive Gray)	55	38	17	69.1%	9
25OTCGN2 G6 Electric tow hook label	83	68	15	81.9%	3
26OMBSI1-EU P7 plus Front Exterior Door Handle Replacement	14	2	12	14.3%	10
26OCGQI1-2 P7plus - Height Sensor Inspection	12	4	8	33.3%	7
24OXDYP1 G6-Reduce the concentration of cleaning fluid	20	19	1	95.0%	0
25OXDCP1 SC–G6 Repair the 12V Battery negative ground point	74	73	1	98.6%	0
EsimTBOX-G6-1 G6-Esim-TBOX delayed claiming	7	6	1	85.7%	0
EsimTBOX-G9-1 G9-Esim-TBOX delayed claiming	3	2	1	66.7%	1
G9MY3231 SC-G9 Pasting the vehicle nameplate	11	10	1	90.9%	0

Workload by campaign type

Campaign-type groupings show where unresolved cases are concentrated.

By campaign type

Segment	Total	Completed	Open	Completion
CIC(Customer Incoming service Campaign)	133	18	115	13.5%
PSC(Pre-delivery Service Campaign)	351	280	71	79.8%
SSC(Special Service Campaign)	181	156	25	86.2%

Completed records by year and quarter

Year	Quarter	Completed	Share of completed
2025	Q1	11	2.4%
2025	Q2	49	10.7%
2025	Q3	12	2.6%
2025	Q4	186	40.7%
2026	Q1	92	20.1%
2026	Q2	64	14.0%
2026	Q3	40	8.8%
2026	Q4	3	0.7%

Vehicle and record attributes

Model, tier and delivery-status breakdowns of all open records. Small groups should be interpreted cautiously.

By vehicle model

Segment	Total	Completed	Open	Completion
G9_2024 AWD Performance	89	15	74	16.9%
New G6 RWD Long Range	194	141	53	72.7%
P7+ RWD Long Range	26	6	20	23.1%
G9_2024 RWD Long Range	24	6	18	25.0%
New G6 AWD Performance	142	126	16	88.7%
New G9 AWD Performance	49	33	16	67.3%
New G9 RWD Long Range	24	18	6	75.0%
G9 AWD Performance	8	4	4	50.0%
G6 RWD Long Range	71	69	2	97.2%
G6 AWD Performance	19	18	1	94.7%
G9_2024 RWD Standard Range	1	0	1	0.0%

Delivery status and data completeness

Operational data gaps limit how confidently the cause or waiting time of open cases can be assessed.

By delivery status

Segment	Total	Completed	Open	Completion
Delivered	667	457	210	68.5%
Unsold	1	0	1	0.0%

By campaign tier

Segment	Total	Completed	Open	Completion
General	397	211	186	53.1%
Important	248	224	24	90.3%
Tier not recorded	20	19	1	95.0%

Missing operational fields

Data check	Missing	Records checked	Missing rate
Open records without a job order	211	211	100.0%
Open records without a completion date	211	211	100.0%
Records without an actual operating store	668	668	100.0%
Records without in-store time	668	668	100.0%
Records without repair status	668	668	100.0%
Records without settlement time	668	668	100.0%

Open cases have no job-order number or completion date; operating store, in-store time, repair status and settlement time are blank zone-wide. The 211 open records cover 171 VINs. Zone, country and service campaign status do not vary in this extract. Check source records before assigning cause or age.

Dealership and campaign hotspots

Top dealership/campaign combinations by open records. Each combination shows its own completion rate and its share of all 211 open zone records.

Dealership	Campaign	Total	Open	Completion	Zone open share
XPENG Service Center Le Cannet x Mozart Autos	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	30	25	16.7%	11.8%
XPENG Service Center Montpellier x GRIM	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	15	15	0.0%	7.1%
XPENG Service Center Aix-en-Provence x Deffeuille	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	11	11	0.0%	5.2%
XPENG Service Center Bandol x Etoile 83	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	9	9	0.0%	4.3%
XPENG Service Center Fréjus Mapauto	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	8	8	0.0%	3.8%
XPENG Service Center Nice x Mozart Autos	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	9	7	22.2%	3.3%
XPENG Service Center Bastia x Groupe SIA	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	6	6	0.0%	2.8%
XPENG Service Center Montpellier x GRIM	**25OYKBN1** New G9/New G6 - UWB Smart Key Update	18	6	66.7%	2.8%
XPENG Service Center Marseille x Parascandola	**25OBTDN1** New G6 Cup Holder Replacement(Impressive Gray)	9	5	44.4%	2.4%
XPENG Service Center Marseille x Parascandola	**25OYKBN1** New G9/New G6 - UWB Smart Key Update	20	5	75.0%	2.4%
XPENG Service Center Marseille x Parascandola	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	5	4	20.0%	1.9%
XPENG Service Center Montpellier x GRIM	**25OTCGN2** G6 Electric tow hook label	15	4	73.3%	1.9%
XPENG Service Center Nîmes x Grim	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	5	4	20.0%	1.9%
XPENG Service Center Perpignan x LG	**25OYKBN1** New G9/New G6 - UWB Smart Key Update	8	4	50.0%	1.9%
XPENG Service Center Aix-en-Provence x Deffeuille	**25OBTDN1** New G6 Cup Holder Replacement(Impressive Gray)	4	3	25.0%	1.4%