

# MEASURED SURVEY AND CONDITION REPORT

Floors 8, 9 and 10, 100 Bishopsgate, London EC2M 1GT

Prepared for

**Bishopsgate Property Holdings Limited**

Carter Mitchell Surveyors LLP, Chartered Surveyors

31 Finsbury Circus, London EC2M 7EA

Reference CMS/23/1187 · 4 December 2023

## 1. Instructions and Scope

1.1 We were instructed by Bishopsgate Property Holdings Limited (the "Client") to measure Floors 8, 9 and 10 of 100 Bishopsgate, London EC2M 1GT (the "Premises") and to record their state and condition ahead of the proposed letting of the Premises to Meridian Consulting Group LLP.

1.2 Our inspection and measured survey were carried out on 21 and 22 November 2023. The Premises were vacant at the time of inspection. This report also forms the basis of the schedule of condition to be annexed to the proposed lease.

## 2. Description of the Premises

2.1 100 Bishopsgate is a multi-storey office building of steel frame construction with glazed curtain walling, completed in 2001 and refurbished in 2018. The Building has a double-height reception at ground floor, six passenger lifts and a goods lift serving all floors, and a basement service yard accessed from Camomile Street.

2.2 The Premises comprise the whole of Floors 8, 9 and 10. Each floor is laid out as open plan office accommodation with raised access floors, suspended ceilings, LED lighting and four-pipe fan coil air conditioning, arranged around a central core containing the lifts, staircases and WCs.

### 3. Measured Areas

3.1 The Premises were measured on site using laser measurement equipment in accordance with the RICS Code of Measuring Practice (6th Edition). Areas are stated on a net internal area (NIA) basis and exclude the central core, plant rooms and common parts.

| Floor        | NIA (sq ft)   | NIA (sq m)     |
|--------------|---------------|----------------|
| Floor 8      | 10,105        | 938.8          |
| Floor 9      | 9,980         | 927.2          |
| Floor 10     | 9,765         | 907.2          |
| <b>Total</b> | <b>29,850</b> | <b>2,773.2</b> |

3.2 The aggregate net internal area of Floors 8, 9 and 10 is 29,850 square feet (2,773 square metres).

3.3 The floor-by-floor variation reflects the stepped curtain wall on the eastern elevation at Floors 9 and 10. Areas are accurate to within plus or minus 0.5 per cent.

### 4. Structure and External Fabric

4.1 The structural frame, floor slabs and curtain walling within and adjoining the Premises were found to be in good condition, with no evidence of movement, cracking or water ingress. Sealant joints to the curtain walling were renewed in 2018 and remain serviceable.

## 5. Internal Condition and Services

5.1 Internal finishes are in good condition throughout, consistent with the 2018 refurbishment. Minor scuffing to wall finishes and isolated stained ceiling tiles were recorded on Floor 9 and are noted in the photographic schedule.

5.2 Mechanical and electrical services serving the Premises, including the fan coil units, lighting and fire detection and alarm systems, were operational at the time of inspection. Service records for the lifts and air conditioning plant are up to date.

## 6. Environmental and Hazardous Materials

6.1 The Building's asbestos register (updated September 2023) records no asbestos containing materials within the Premises. No deleterious materials were identified during our inspection.

6.2 The Premises hold an Energy Performance Certificate with a rating of B, valid until 2028. We are not aware of any contamination affecting the Building or its site.

## 7. Summary

7.1 The Premises are in good condition and suitable for occupation as offices without the need for significant works. The measured areas in section 3 should be used for the purposes of the proposed letting.

### **Carter Mitchell Surveyors LLP**

31 Finsbury Circus, London EC2M 7EA · 4 December 2023