HOMEWORN SCUTION MER314: ADV. STREWETH OF MIC. PROB 7.33 PG 1 07 3 BUDYNAS, 200

PROBLEM 7.33 DETERMINE THE MANIMUM TRESCH AND HONMISES STRESSES FOR THE GIVEN STRESS MATRIX. COMPANE THE HON MISES STRESS WITH TWO TIMES THE TRESCA STRESS.

GIVEN: 1. $T_{\lambda} = T_{y} = T_{z} = 20 \text{ mPa}$ 2. $Y_{yz} = Y_{xz} = Y_{xy} = 10 \text{ mPa}$

ASSCMPTICN:

1. LINBOR GLASTIC MINTERIAL


2. SMALL DEFERMATIONS

FIND:

1. MAXIMUM TRESCH STRESS.

2. MAXIMUM HON MISSES STRESS WITH TWO TIMES THE TRENCH STRESS

PIGULE



```
>> S=[20 10 10; 10 20 10; 10 10 20]
S =
 20 10 10
  10 20 10
  10 10 20
>> [EV,PS]=eig(S)
EV =
 0.7071 \quad 0.4082 \quad 0.5774
 -0.7071 0.4082 0.5774
    0 -0.8165 0.5774
PS =
  10 0 0
  0 10 0
  0 0 40
>> EV'*S*EV
ans =
 10.0000 0.0000 0.0000
  0.0000 10.0000 -0.0000
       0 -0.0000 40.0000
```


HOMEWORK SOLUTION MER311: ADV. STRENGTH OF MITC. PROB 7.33 PG2 OF 3 BUDYNAS 2 NO.

THE PRINCIPAL STRESSES ARE GIVEN BY

T1 = 40 mPa, T2 = 03 = 10 mPa

1

A QUICK DRAWING OF MOHR'S CIRCLE WILL HELP TO MISCALIZE THES STATE



HOMEWORK SCUTICN MER311: ADV. STREWOTH OF MITL PROB 7.33 Pg 3 cf 3
BUDTNAS 2 NO

THE HON MISES STRESS IS CALLLIATED FROM THE PRINCIPAL SMEJSES

$$\mathcal{T}_{ym} = \sqrt{0.5 \cdot [(\mathcal{T}_1 - \mathcal{T}_2)]^2 + (\mathcal{T}_1 - \mathcal{T}_3)^2 + (\mathcal{T}_2 - \mathcal{T}_3)^2} \\
= \sqrt{0.5 \cdot [(10 - 10)]^2 + (10 - 40)^2 + (10 - 40)^2} = \sqrt{0.5 \cdot 2 \cdot (10 - 40)^2} = \sqrt{(30 \text{ m/Ba})^2} \\
= \sqrt{30 \text{ M/Pa}} \qquad \boxed{2}$$

THE Maximus TRESCH STRESS IS SEEN IN 8 45

Summary

MOUR'S CIRCLE IS NOT REQUIRED FOR THIS PROBLEM BUT IT DOES HELP TO HIS CHOIZE THE STRESS FIELD. NOTE THAT THE THREE CINCLES THAT MAKE UP MOHRS CIRCE REDUCE TO A SONGLE CIRCLE IN THIS POLCBLEM.