

As a student at Union College, I am part of a community that values intellectual effort, curiosity and discovery. I understand that in order to truly claim my educational and academic achievements, I am obligated to act with academic integrity. Therefore, I affirm that I carried out the work on this exam with full academic honesty, and I rely on my fellow students to do the same.

For this Exam, I understand that:


1. I **must** work alone in writing out the solutions to the problems in this exam.
2. I **cannot** copy solutions, in part or whole, to the problem on this exam from any person or resource.
3. I **cannot** use any electronic resources to assist me in the solution to the questions on this exam except for my calculator to only performing appropriate calculations on the exam.
4. I **can** use one page - single sided - of notes during the exam. This one page of notes **cannot** contain any solutions to problems. **I must staple this page to the back of my exam at the end of the exam.**

Signature: _____


Print Name: SOLUTION

Exam Date: 7 JUNE 2016

PROBLEM 1: A horizontal beam AB is supported by a pinned-end column CD, as shown in the figure. The column CD is a solid steel bar ($E=200$ GPa) of square cross section having length 1.8m and side dimensions $b=50\text{mm}$ ($I = \frac{1}{12} \cdot b \cdot h^3$).



1a. Using the freebody diagram below, determine the load in member CD.



1b. Based upon the critical load of the column, determine the allowable load Q with respect to buckling.

FOR THE PINNED-PINNED CASE


$$P_{CR} = \frac{\pi^2}{L^2} \cdot E \cdot I$$

$$3Q = \frac{\pi^2}{(1.2m)^2} \cdot 200(10^9) \frac{N}{m^2} \cdot 520.8(10^{-9}) m^4$$

$$Q = \frac{\pi^2}{3 \cdot (1.2m)^2} \cdot 200(10^9) \frac{N}{m^2} \cdot 520.8(10^{-9}) m^4$$

$$= \boxed{105.8(10^3) N}$$


PROBLEM 2: Below is a $\frac{1}{2}$ -in pitch roller chain plate, as used on a bicycle chain. Since a roller chain cannot transmit compression, the link is loaded in repeated axial tension (load fluctuates between 0 and a maximum force as the link goes from the slack side to the tight side of the chain) by pins that go through the two holes shown.



2a: Using the graph paper on the next page, draw the Modified Goodman diagram for this problem. The link is made of carbon steel, heat-treated to give $S_u = 140 \text{ ksi}$ and $S_v = 110 \text{ ksi}$. All surfaces are comparable to the "machined" category. Use the conservative estimate of Notch Sensitivity $q=1.0$.

$$S_c' = 0.5 \cdot S_{ut} = 0.5 \cdot (140 \text{ ksi}) = 70 \text{ ksi}$$

$$S_e = (0.69) \cdot (1) \cdot (0.85) \cdot 70 \text{ ksi} = 41.1 \text{ ksi}$$



 LOAD FACTOR (AXIAL LOADING)
 SIZE EFFECT (AXIAL LOADING)
 SURFACE FINISH (SEE CHART)

From THE FIGURE

$$K_t \approx \text{STATIC STRESS CONCENTRATION FACTOR} \left(F_C N \frac{d}{D} = \frac{0.125}{0.382} = 0.327 \right)$$

$$= 2.3$$

$$\begin{aligned}
 K_f &\approx \text{FATIGUE STRESS CONCENTRATION FACTOR } (q=1) \\
 &= 1 + q \cdot (K_t - 1) = 1 + 1 \cdot (2.3 - 1) \\
 &= \underline{\underline{2.3}} \quad (\text{TO BE USED ON THE NOMINAL STRESS})
 \end{aligned}$$



2b. Estimate the [maximum tensile force to prevent yielding for static loading] and [the maximum tensile force for a static factor of safety of 2.]

THE MAXIMUM STRESS WILL OCCUR AT THE PIN HOLES

$$\sigma = K_T \cdot \frac{F}{A} = 2.3 \cdot \frac{F}{(0.05\text{in})(0.382\text{in} - 0.125\text{in})} = 110 \text{ ksi};$$

$$\Rightarrow F = \frac{110(10^3) \frac{\text{lb}}{\text{in}^2} \cdot (0.05\text{in}) \cdot (0.382\text{in} - 0.125\text{in})}{2.3} = \boxed{615 \text{ lb}}$$

STATIC LOAD
TO PREVENT
YIELD

STATIC LOADING TO PREVENT YIELDING USING A FACTOR OF SAFETY OF 2


$$\sigma = K_T \cdot \frac{F \cdot n}{A} = \frac{2.3 \cdot F \cdot 2}{(0.05\text{in})(0.382\text{in} - 0.125\text{in})} = 110 \text{ ksi};$$

$$\Rightarrow F = \frac{110(10^3) \frac{\text{lb}}{\text{in}^2} \cdot (0.05\text{in}) \cdot (0.382\text{in} - 0.125\text{in})}{2 \cdot 3 \cdot 2} = \boxed{307 \text{ lb}}$$

STATIC LOAD TO
PREVENT YIELD
USING F.S. = 2

2c. Estimate the maximum tensile force that will give infinite fatigue life. Draw the fatigue stresses on the Modified Goodman Diagram in part 2a. What is the tensile force for a fatigue factor of safety of 1.2?

THE LOADS ARE GO FROM 0 TO MAXIMUM



THE EQUATION OF THE GOODMAN LINE

$$\sigma_a = m \cdot \sigma_m + b = -0.2936 \cdot \sigma_m + 41.1 \text{ ksi}$$

$$b = 41.1 \text{ ksi } (Se)$$

$$m = \frac{-41.1 \text{ ksi}}{140 \text{ ksi}} = -\frac{Se}{S_{cr}} = -0.2936$$

POINT A IS THE INTERSECTION OF THE LOAD LINE AND THE MODIFIED GOODMAN LINE. POINT A'S LOCATION IS

$$\sigma_m^{(A)} = \sigma_a^{(A)} = -0.2936 \cdot \sigma_m^{(A)} + 41.1 \text{ ksi}$$

$$1.2936 \cdot \sigma_m^{(A)} = 41.1 \text{ ksi} \Rightarrow \sigma_m^{(A)} = \sigma_A^{(A)} = \frac{41.1 \text{ ksi}}{1.2936} = \underline{\underline{31.77 \text{ ksi}}}$$

OA ALONG THE LOAD LINE IS

$$OA = \sqrt{2 \cdot (31.77 \text{ ksi})^2} = 44.93 \text{ ksi}$$

THE MAXIMUM TENSILE FORCE FOR INFINITE LIFE

$$\frac{F}{2} = \sigma_A = \sigma_m \Rightarrow \sigma = 2\sigma_A = K_f \cdot \frac{F}{A}$$

$$\Rightarrow F = \frac{2 \cdot \sigma_A \cdot A}{K_f} = \frac{2 \cdot (31.77 \times 10^3 \text{ lb/in}^2) \cdot (0.382 \text{ in} \times 0.125 \text{ in}) \cdot 0.05 \text{ in}}{2.3} =$$

355 lb

MAY LOAD FOR INFINITE LIFE

CALCULATING THE MAXIMUM LOAD FOR INFINITE LIFE
AND A FACTOR OF SAFETY OF 1.2

$$F.S. = n = \frac{Q_A}{Q_B} \Rightarrow Q_B = Q_A = \frac{44.93 \text{ ksi}}{1.2} = 37.44 \text{ ksi.}$$

Now $\sigma_a^{(B)}$ AND $\sigma_m^{(B)}$ CAN BE CALCULATED

$$\sigma_a^{(B)} = \sigma_m^{(B)} = \sqrt{\frac{(CB)^2}{2}} = \sqrt{\frac{(37.44 \text{ ksi})^2}{2}} = 26.48 \text{ ksi.}$$


THE MAXIMUM TENSILE FORCE

$$\frac{\sigma}{2} = \sigma_a^{(B)} = \sigma_m^{(B)} \Rightarrow \sigma = 2 \cdot \sigma_a^{(B)} = 2 \cdot \sigma_m^{(B)} = K_f \cdot \frac{F}{A}$$


$$\Rightarrow F = \frac{2 \cdot \sigma_a^{(B)} \cdot A}{K_f} = \frac{2 \cdot (26.48 \times 10^3 \frac{\text{lb}}{\text{in}^2}) \cdot (0.05) (0.382 \text{ m} - 0.125 \text{ m})}{2.3}$$

$$= \boxed{296 \text{ lb}}$$

MAX LOAD FOR
INFINITE LIFE AND
A FACTOR OF SAFETY OF 1.2



Fatigue Surface Finish Factor Chart



Static Stress Concentration Factor

$$\frac{d}{D} = \frac{0.125}{0.382} = 0.327$$

As a student at Union College, I am part of a community that values intellectual effort, curiosity and discovery. I understand that in order to truly claim my educational and academic achievements, I am obligated to act with academic integrity. Therefore, I affirm that I carried out the work on this exam with full academic honesty, and I rely on my fellow students to do the same.

For this Exam, I understand that:


1. **I must** work alone in writing out the solutions to the problems in this exam.
2. **I cannot** copy solutions, in part or whole, to the problem on this exam from any person or resource.
3. **I cannot** use any electronic resources to assist me in the solution to the questions on this exam except for my calculator to only performing appropriate calculations on the exam.
4. **I can** use one page - single sided - of notes during the exam. This one page of notes **cannot** contain any solutions to problems. **I must staple this page to the back of my exam at the end of the exam.**

Signature: _____


Print Name: _____

Exam Date: _____

PROBLEM 1: A horizontal beam AB is supported by a pinned-end column CD, as shown in the figure. The column CD is a solid steel bar ($E=200 \text{ GPa}$) of square cross section having length 1.8m and side dimensions $b=50\text{mm}$ ($I = \frac{1}{12} \cdot b \cdot h^3$).




1a. Using the freebody diagram below, determine the load in member CD.




1b. Based upon the critical load of the column, determine the allowable load Q with respect to buckling.

PROBLEM 2: Below is a $\frac{1}{2}$ -in pitch roller chain plate, as used on a bicycle chain. Since a roller chain cannot transmit compression, the link is loaded in repeated axial tension (load fluctuates between 0 and a maximum force as the link goes from the slack side to the tight side of the chain) by pins that go through the two holes shown.




2a: Using the graph paper on the next page, draw the Modified Goodman diagram for this problem. The link is made of carbon steel, heat-treated to give $S_u=140$ ksi and $S_y=110$ ksi. All surfaces are comparable to the “machined” category. Use the conservative estimate of Notch Sensitivity $q=1.0$.




2b. Estimate the maximum tensile force to prevent yielding for static loading and the maximum tensile force for a static factor of safety of 2.

2c. Estimate the maximum tensile force that will give infinite fatigue life. Draw the fatigue stresses on the Modified Goodman Diagram in part 2a. What is the tensile force for a fatigue factor of safety of 1.2?



Fatigue Surface Finish Factor Chart



Static Stress Concentration Factor

