# Honeywell

### Interactive Catalog Replaces Catalog Pages

Honeywell Sensing and Control has replaced the PDF product catalog with the new Interactive Catalog. The Interactive Catalog is a power search tool that makes it easier to find product information. It includes more installation, application, and technical information than ever before.



Click this icon to try the new Interactive Catalog.

### **Sensing and Control**

Honeywell Inc.
11 West Spring Street
Freeport, Illinois 61032

# Absolute, Differential, Gage, Vacuum Gage/Amplified



### **FEATURES**

- PCB terminals on opposite side from the ports
- Fully signal conditioned

### 140PC SERIES PERFORMANCE CHARACTERISTICS at 8.0 $\pm$ 0.01 VDC Excitation, 25°C

	Min.	Тур.	Max.	Units		
Excitation	7.00	8.00	16.0	VDC		
Supply Current		8.00	20.0	mA		
Current Sourcing Output			10	mA		
Null Offset (141/142PC)	0.95	1.00	1.05	V		
Null Offset (143PC)*	3.45	3.50	3.55	V		
Null Offset 142PC15A @ 2 psia 142PC30A @ 2 psia	1.62 1.28	1.67 1.33	1.72 1.38	V V		
Output at Full Pressure	5.90	6.00	6.10	V		
Span† (141/142PC)	4.95	5.00	5.05	V		
Span† (143PC)*		5.00		V		
Span 142PC15A (2 to 15 psia) 142PC30A (2 to 30 psia)	4.28 4.62	4.33 4.67	4.48 4.72	V V		
Ratiometricity Error 7 to 8 V or 8 to 9 V 9 to 12 V		±0.50 ±2.00		%Span		
Stability over One Year		±0.50		%Span		
Response Time			1.00	msec		
Common Mode Pressure * *			40	psi		
Weight		28		grams		
Short Circuit Protection	Output	Output may be shorted indefinitely to ground				
Output Ripple	None, D	None, DC device				
Ground Reference	Supply	Supply and output are common				

### **ENVIRONMENTAL SPECIFICATIONS**

Operating Temperature	-40° to +85°C (-40° to +185°F)
Storage Temperature	−55° to +125°C (−67° to +257°F)
Compensated Temperature	-18° to +63°C (0° to +145°F)
Shock	MIL-STD-202, Method 213 (50 g, half sine, 6 msec)
Vibration	MIL-STD-202, Method 204 (10 to 2000 Hz at 10 g)
Media	P2 port Wetted materials; polyester housing, epoxy adhesive, silicon, borosilicate glass, and silicon-to-glass bond*
	P1 port Dry gases only

<sup>\*</sup>Liquid media containing some highly ionic solutions could potentially neutralize the chip-to-glass tube

<sup>\*</sup>Positive and negative pressure measurement.

\*\*Higher common mode pressures possible if sensor is not used over entire operating temperature range.

†Span is defined as the algebraic difference between end points. Please note: actual output is 1 V to 6 V (at 8.00 ±0.01 VDC). Span is then 5V.

**Pressure Sensors** 140PC Series

# Absolute, Differential, Gage, Vacuum Gage/Amplified

### 140PC SERIES ORDER GUIDE, VACUUM GAGE TYPE

		1	Null, Sensi	Shift tivity, Combin	ed**			Linearity,	1	
	Dunnanuna	25 t	:o 5°	25 to -18°	25 to −40°	1	0	P2 > P1	P2 < P1	Repeatability
Catalog	Pressure 25 to 45°C		25 to +63°C	o +63°C 25 to 85°C	Sensitivity	Overpressure psi	%Span		& Hysteresis %Span	
Listing	psi	Тур.	Max.	Max.	Max.	V/psi	Max.	Max.	Max.	Тур.
141PC01G	01		±1.50			5.000	20		±0.75	±0.30
141PC05G	05	±0.50		±1.00	±2.00	1.000	20		±0.75	±0.25
141PC15G	015	±0.50		±1.00	±2.00	0.333	45		±0.40	±0.15

### 140PC SERIES ORDER GUIDE, GAGE TYPE

		1	Null, Sensi	Shift tivity, Combin	ed**			Linearity, B.S.F.L.		
	Pressure	25 to 5°		25 to −18°	25 to −40°	Overpressure Sensitivity psi	Overpressure	P2 > P1	P2 < P1	Repeatability & Hysteresis
Catalog	Range	25 to	25 to 45°C   25 to +63°C   25 to 85°C		25 to 85°C		% Span		%Span	
Listing	psi	Тур.	Max.	Max.	Max.	V/psi	Max.	Max.	Max.	Typ.
142PC01G	0-1		±1.50			5.000	20	±0.75		±0.30
142PC02G	0-2		±1.50			2.500	20	±0.75		±0.30
142PC05G	0-5	±0.50		±1.00	±2.00	1.000	20	±1.50		±0.25
142PC15G	0-15	±0.50		±1.00	±2.00	0.333	45	±0.75		±0.15
142PC30G	0-30	±0.50		±1.00	±2.00	0.167	60	±0.75		±0.15
143PC03G	±2.5			±1.00	±1.50	1.000	20	±0.75		±0.25
143PC05G	±5			±1.00	±1.50	0.500	30	±0.75		±0.15
143PC15G	±15			±1.00	±1.50	0.177	50	±0.75		±0.15

### 140PC SERIES ORDER GUIDE, DIFFERENTIAL TYPE

		1	Null, Sensi	Shift tivity, Combin	ed**			Linearity, B.F.S.L.			
	Pressure	25 t	o 5°	25 to -18°	25 to −40°		Overnmenous	P2 > P1	P2 < P1	Repeatability	
Catalog	Range	25 to	45°C	25 to +63°C	25 to 85°C	Sensitivity	Overpressure psi	%Sp	oan	& Hysteresis %Span	
Listing	psi	Тур.	Max.	Max.	Max.	V/psi	Max.	Max.	Max.	Typ.	
142PC01D	0-1		±1.50			5.000	20	±0.75	±0.40	±0.30	
142PC02D	0-2		±1.50			2.500	20	±0.75	±0.40	±0.30	
142PC05D	0-5	±0.50		±1.00	±2.00	1.000	20	±1.50	±0.75	±0.25	
142PC15D	0-15	±0.50		±1.00	±2.00	0.333	45	±0.75	±0.40	±0.15	
142PC30D	0-30	±0.50		±1.00	±2.00	0.167	60	±0.75	±0.40	±0.15	
143PC03D	±2.5			±1.00	±1.50	1.000	20	±0.75	±0.40	±0.25	
143PC05D	±5			±1.00	±1.50	0.500	30	±0.75	±0.40	±0.15	
143PC15D	±15			±1.00	±1.50	0.177	50	±0.75	±0.40	±0.15	

### 140PC SERIES ORDER GUIDE, ABSOLUTE TYPE\*

		Shift Null, Sensitivity, Combined**						Linearity,	1	
	Pressure	25 t	o 5°	25 to −18°	25 to −40°		Overpressure	P2 > P1	P2 < P1	Repeatability & Hysteresis
Catalog	Range	25 to	45°C	25 to +63°C	25 to 85°C	Sensitivity	psi	%S <sub>I</sub>	oan	%Span
Listing	psia	Тур.	Max.	Max.	Max.	V/psi	Max.	Max.	Max.	Тур.
142PC15A	0-15	±0.50		±1.00	±2.00	0.333	45		±0.40	±0.15
142PC30A	0-30	±0.50		±1.00	±2.00	0.167	60		±0.40	±0.15

38


Honeywell ● Sensing and Control ● 1-800-537-6945 USA ● +1-815-235-6847 International ● 1-800-737-3360 Canada

<sup>\*</sup>Tested at 2 psia reference
\*\*% Span specification applies to each shift independently. (Null, sensitivity, or combined).

### **Pressure Sensors**

### Absolute, Differential, Gage, Vacuum Gage/Amplified


# **ELECTRICAL CONNECTION**Voltage Excitation




#### NOTES

- 1. Terminals are labeled on the sensor.
- 2. Input and output share a common ground.
- R<sub>L</sub> must be greater than or equal to 3000 ohms.

### INTERNAL CIRCUITRY



### **RATIOMETRICITY**



Ratiometricity refers to the output voltage being directly proportional to the supply voltage. 140PC sensors in this catalog are calibrated at 8 VDC supply voltage to provide a 1-6 volt (5V Span) output swing. For example, if supply increases by 50% to 12 VDC, the output voltage increases by 50% to 1.5-9 volts (7.5 V Span).

### **NOTE**

The output is not perfectly ratiometric. See specifications for the degree of error.


# NULL AND SENSITIVITY TEMPERATURE SHIFT

Amplified pressure sensors are 100% tested to insure that the maximum null and sensitivity temperature shift does not exceed the specification. The diagram below illustrates how null and sensitivity shift relates to temperature. Note that the maximum shift occurs at temperature extremes. Therefore, if a sensor is not ex-


posed to the entire temperature range, the maximum null and sensitivity shift will actually be less than the value specified.

This diagram indicates the temperature shift pertaining to a few listings. Maximum null and sensitivity shift varies from listing to listing.

#### NULL AND SENSITIVITY SHIFT (% F.S.O.)



### **SCALING OF 140PC SERIES SENSORS WITH 8V EXCITATION**



142PC15A	Absolute	$V_{\circ} = 1 \text{ V at 0 psia \& 6 V at 15 psia}$
142PC30A	Absolute	$V_{\circ} = 1 \text{ V at 0 psia \& 6 V at 30 psia}$
142PC15G	Gage	V <sub>o</sub> = 1 V at 0 psig & 6 V at 15 psig
141PC15G	Vacuum Gage	$V_{\circ} = 1 \text{ V at 0 psig \& 6 V at } -15 \text{ psig}$
143PC05D	Differential	V₀ = 1 V at −5 psig & 6 V at 5 psig
143PC15D	Differential	V <sub>o</sub> = 1 V at −15 psig & 6 V at 15 psig

NOTE: 141PC sensors are scaled for vacuum pressure on P2.


142PC sensors are scaled for greater pressure on the P2 side of the chip. Input pressures on absolute units are applied to the P1 port.

Other scalings available upon request.

**Pressure Sensors** 140PC Series

# Absolute, Differential, Gage, Vacuum Gage/Amplified

### **MOUNTING DIMENSIONS** (For reference only)



Dimensions shown apply to Differential and Absolute versions. Gage units are identical, except the P1 port is absent.

### 140PC CONSTRUCTION

