## **Hunterbilt Industries Ltd.**

PO Box 137 Telkwa, BC V0J 2X0



Invoice #2920

Issued 07/05/2019

Due 06/06/2019

Phone 250-846-5343

Email hunterbilt@gmail.com

Website hunterbilt.ca
Service Address 101 Weston St.

Winnipeg, Manitoba R3E 2T4

**LOBLAW INC. - Shoppers Drug Mart Smithers Store #2257** 101 Weston St. Winnipeg, Manitoba R3E 2T4

## PO # 4200373451 - BC 591791 - BACK ROOM DAIRY COOLER TOO WARM.

SERVICE / PRODUCT	DESCRIPTION	QTY.	UNIT COST	TOTAL
05/04/2019				
Labour Commercial	Found compressor short cycling due to failed current start relay.  Ohmed Compressor and all good. Installed temporary hard start and run kit for now.  Ordered correct parts as needed.	2	\$95.00	\$190.00
TEC RELAY	K71-02-TEC	1	\$32.91	\$32.91
TEC OVERLOAD	K90-35-TEC	1	\$58.25	\$58.25
START CAP. 161- 193MFD 165V	161-192-165V-MAR	1	\$23.38	\$23.38
06/05/2019				
Labour Commercial	Installed starting relay and parts needed. Turned on and tested. All good. Amperage 8.8 ( RLA 9 )	1.5	\$95.00	\$142.50

Thank you for your business. Please contact us with any questions regarding this invoice.

GST 84747 6058 RT0001

Total	\$469.39
GST (5.0%	\$22.35
Subtotal	\$447.04