



Invoice No.: 578581 Invoice Date: 07/16/2019 Client: L100721-1421 Site: 6390AAA-1411

Page: 1 of 3

Loblaws Inc ATTN: Miro Processing 101 Weston St Winnipeg MB R3E 2T4 Service Location Shoppers Drug Mart #2324 Hinton 10-632 Carmichael Lane Hinton AB T7V 1S8

Work Order Id: 675024 P.O. #: 4200383126/PR604415 Completion Date: 06/04/2019 Job Id: 12NABSR101885

Work Requested:

The freezer has been alarming all weekend not temping propoerly

Labor Charges						Ext'd Price
Mike Wieschorster	06/04/2019	HRS.	4.50	@	\$102.0000	\$459.00
Mat/Oth/Sub Charges						Ext'd Price
Gateway Truck Charge		QTY	1.00	@	\$35.0000	\$35.00
		SUBTOTAL GST 5% 101960383 INVOICE TOTAL			\$494.00 \$24.70 \$518.70	

NET 30 DAYS

Please remit to:

Gateway Mechanical Services Inc 14605 118 Ave Edmonton, AB T5L 2M7 Toll Free: 1.800.414.4929

Questions about your invoice?

We can help: clientcare@gatewaymechanical.ca







Work Order # 675024 Details					
Caller	Lisa 780-865-5132				
Date Created	2019-06-03				
Purchase Order	PR604415				
Date Completed	June 24, 2019 - 1:57:34 p.m.				
Technician	Mike Wieschorster				

Site Information	Billing Information	
Shoppers Drug Mart #2324 Hinton	Loblaws Inc	
10-632 Carmichael Lane	101 Weston St	
Hinton, AB T7V 1S8	Winnipeg, MB R3E 2T4	
Phone: (780)865-5132		

Work Requested

The freezer has been alarming all weekend not temping propoerly

Equipment Name: 13 Door Freezer 3 Model:

<u>Manufacturer:</u>
Serial Number:

Work Performed

Drove to site then had lisa show me which section of freezers were warm. All freezer cases were below -20°C and the alarms had went away. Checked case airflow and found that the system 3 had low airflow. Checked defrost circuit and found that there were two fuses blown. Checked case history and found that we had this problem back in January and therefore should replace the heaters so they don't keep blowing the fuses.

I have submitted a recommend repair to our estimating team and have followed up with them so the quote could be rushed out. Drove to site and had Lisa show me which sections of the freezer were warm. All freezer cases were below -20°C and alarms were no longer present. Checked case airflow and found that system 3 had lower airflow than the rest.

Checked defrost circuit and found the fuses had blown. I checked the case history and found that this has been an ongoing issue and therefore we should replace the defrost heaters. Submitted quote info to our estimating department and asked the quote to be rushed out.

		Summary				
		Labor Detail				
Technician	Equipment	Labor Type Id	Date		Hours	
Mike Wieschorster	RCS3	HVACR-JRNY-RT	2019-06-04		4.5	
				Total	4.5	
		Material / Misc / Flat Ra	ate Details			
Equipment	Item	Description				Quantity

Customer Signature

Customer Name: Mike Wieschorster

Customer signature indicates acceptance of charges

Location Upon Signature