Tradewinds Refrigeration & Air Conditioning Ltd.

2016 3a St S

Cranbrook, British Columbia V1C 1G9

Canada

Phone: (250) 426-2199

Fax:

INVOICE

Invoice No.:

23026

Date:

03/29/2019

Purchase Order:

4200368818

Sold to:

Loblaws Inc. (RCSS)

Attn: LPL MIRO Processing 101 Weston Street Winnipeg, Manitoba R3E 2T4

Canada

		Description			item No.	Amount
March.15th, 2019 RE: RCS Seafood Bunker too warm nspect 8ft seafood coffin fr ase temperature and airflo	eezer, found poor ai	flow caused by ice build	d-up. De-iced ca	ase, verified prop	per	
.5 hrs			eq.		Labour	242
VO#30322245 sset ID# 1553-159	7.5		<u></u>		Vehicle Charge	28
6 - GST 5.00% SST	ž.	ч .	n		e se	2
o i		* .				13
	·	±	a s		d	¥
	2				-	
		i) Fi		t o a		
		1				g 65.0
		a a				
	*	*			n - r	
Ţ	e .	•				20
			Œ			
5				(i		В
-		£	-01	is a	*	
				2		gr G
		v = *	=		U S	e e ²
				T		ta a
adewinds Refrigeration &		GST: #13707 7079 RT	0001			4 g
nipped By:	Fracking Number:					

LOBLAWS INC.

DATE W.O. ISSUED STORE # WORK ORDER NUMBER MAINTENANCE DAILY WORK ORDER 03/19 The Contractor Personnel has showed proof of Loblaw Contractor Safety Orientation? ☐ YES The Contractor Personnel represents and warrants that it will perform work in accordance with applicable health & safety legislation ☐ YES □ NO and regulations and all applicable legislation and standards governing the work. Contractor Personnel has signed-in on the Visitor's Log and obtained a visitor's badge. ☐ YES □ NO The Facilities Emergency Procedures have been reviewed. 4. ☐ YES □ NO 5. The Scope of the Contractors Work has been reviewed. ☐ YES Contractor Personnel has been informed of the presence of Asbestos (if applicable) and has been afforded the opportunity to review ☐ YES □ N/A the Asbestos Building Materials Assessment. Contractor Personnel have reviewed any hazards associated with the work being performed and the ☐ YES □ NO with Store Manager or Designate. CONTRACTOR PERSONNEL STORE MANAGER OR DESIGNATE SIGNATURE: STEUE MAC NET Signature **REAL CANADIAN SUPERSTORE #1553 TRADEWINDS REFRIGERATION &** 2100 - 17th STREET NORTH AIR CONDITIONING LTD. 2016 3A'ST. S. CHANBROOK, BG CRANBROOK, B.C. V1C 1G9 V1C 7J1 03 bunker freezer too warm Model # OWIZUB Inspected coffin freezer Deficed case, verified. Case temperature and a REFRIGERATION CONTRACTORS ONLY> REFRIGERANT TYPE: ODP# TECHNICIAN HAS REPORTED TO > > > > > > MINISTRY / DEPT, OF ENVIRONMENT OR ATTACH FAX YES > SEND LEAK REPORT TO LOBLAWS INC. COST/KM REG. HOURS OVERTIME 1. Pobert MATERIAL LABOUR O М TRUCK CHARGE U KM COST М R OTHER S R GST / HST

AMOUNT DUE