



Online guide

Fan housing with rewind starter

1142 080 2102


Bin **02** | 1 spare per kit | **S2** supervision

MS 462 — rewind starter

Includes items 2–15. Mounts to the crankcase with three pan head screws **9022 371 1020** (IS M5×20; item 17).

Item 1 | Qty fitted: 1

MS 462 C-M — ITEM 1



MS 462 C-M Z spare-parts list, 10/29/2024.
Section O; PDF drawing p. 21, parts table p. 22.

Drawing © ANDREAS STIHL AG & Co. KG. Not to scale.

2026-09-27