
Längsschnitt A - A 1:100






Foto 006

Foto: Aegerter & Bosshardt (2020)

Foto (001)

Foto: NSNW (HI 2019)

Foto (002)

Foto: NSNW (HI 2019)

Foto (003)

Foto: Aegerter & Bosshardt (2020)

Foto (004)

Foto: Aegerter & Bosshardt (2020)

Foto (005)

Foto: NSNW (HI 2019)

Foto 007

Foto: Aegerter & Bosshardt (2020)

Foto 008

Foto: Aegerter & Bosshardt (2020)

Foto (009)

Foto: Aegerter & Bosshardt (2020)

Foto (010)

Querschnitt B - B

⋖ FBBS

Korrosion möglich

hohes Korrosionsrisiko

30.07.2021


Hohlkasten Innen / WL-Kammer

Untersicht

Belagsfenster Sondierstellen

Ansicht

1:50



FBZH ▶

