

STEPS CREATED BY WALDO. REFER TO WALDO/ORCA FOR MORE INFORMATION

PLACE (2) 1X64 SPLITTERS MODULE PFPSCAPC1X64PNP=2 IN SLOTS 5-8.
PFP ADDRESS 9400.2 W BROWARD BLVD PFP. SPT2101LA,129-256

1 845C
2 845C
3 845C
4 845C

REMO (4) 1X32 SPLITTERS. SPT2101LA, 1-128 FROM SLOTS 1-4. PFP ADDRESS 9400.2 W BROWARD BLVD PFP

PLANNER COMMENTS: TURN DOWN AND DECOM SPLITTERS 1-4. REMOVE SPLITTER 1-4. THEY HAVE NO WORKERS AND THEY ARE NON GPON.

5 845M 12 TERM Fiber Assignment
Status
CLLI
Cable
RR Info
ASSIGNED
FTLDFLJA
JA020, 845-846
RACK: 010108.23 PANEL: 4 JACK: 197-198
SPLITTER
FTLDFLJA
SPT2101LA, 129-256

| PROJECT # A059AAP | | DATE SVC REQ'D 02/26/2026 | |) |
|-------------------|-------------------------|------------------------------|------------------|----|
| DA | GEO LOC E4512 | | clli ftldflja | |
| DRIMARY ENGR : H | JERNΔ | NDF7 | PERE7 | RΔ |

ENGR. ID: RH7060 PERMIT REQ'D. N

PHONE #: 3053410749 PRINT 1 OF 1