- ■焼入れ性が良好。空冷で硬化します。(空冷のため、焼割れの心配があ りません。)
- ■熱処理変形が非常に小さく、精度の必要な型に最適です。
- ■大型品でも硬さのムラがなく、空冷による焼入れが可能です。
- ■耐摩耗性はSKS3に比べ良好です。
- ■焼入れ性が良く、真空熱処理に最適です。

■一般金型用



注文方法 材質·T(厚さ)×A(長さ)×B(幅)=枚数

Α	В	T(厚さ)							
(長さ)	(幅)	8	10	13	15	16	20	22	25
60		0	0	0	0	0	0	0	0
80	60	0	0	0	0	0	0	0	0
500		0	0	0	0	0	0	0	0
63	63	0	0	0	0	0	0	0	0
80		0	0	0	0	0	0	0	0
80	80	0	0	0	0	0	0	0	0
100		0	0	0	0	0	0	0	0
125		0	0	0	0	0	0	0	0
150		0	0	0	0	0	0	0	0
160		0	0	0	0	0	0	0	0
180		0	0	0	0	0	0	0	0
200		0	0	0	0	0	0	0	0
210		0	0	0	0	0	0	0	<u> </u>
250		0	0	0	0	0	0	0	0
300		0	0	0	0	0	0	0	0
500		0	0	0	0	0	0	0	0
100	100	0	0	0	0	0	0	0	0
125		0	0	0	0	0	0	0	0
150		<u> </u>	0	0	0	0	0	0	0
160		0	0	0	0	0	0	0	0
180		0	0	0	0	0	0	0	0
200		0	0	0	0	0	0	0	0
210		0	0	0	0	0	0	0	0
250		0	0	0	0	0	0	0	0
300		0	0	0	0	0	0	0	0
350		0	0	0	0	0	0	0	0
400		<u> </u>	0	0	00	0	0	0	0
450		0	0	0	0	0	0	0	0
500		<u> </u>	0	0	00	0	0	0	0
125	125	0	0	00	0	0	0	00	0
150									
160		0	0	0	0	0	0	0	0
180		0	0	0		0	0		
200			-	0	0	0	0	0	
210 250		0	0	0		0	0		0
				0	0	0	0		
300 350		0	0	0	0		0		0
400		0	0	0	0	0	0		
400		0	0	0	0	0	0		0
500		0	0	0	0	0	0		0
			<u> </u>						