

| Date | | 2016-06-16 |
|--|--------------|--|
| Manifest | | WC-06162016-VV-SC |
| Driver's Name | | Sergio Cortes |
| Driver's Signature | | |
| Recieving Facility | | 2586 Shenandoah Way, San Bernadino, CA San Bernadino (Division W) |
| Restaurant Name | | <u>Victor Valley Waste Water</u> |
| Restaurant Rep | | EUGENE A |
| Restaurant Rep Signature | | |
| | | Generator not available for Signature |
| Address: 20111 SHAY R | OAD VICTO | RVILLE, CA |
| Grease Trap Size | | |
| | | |
| | Otv | Collected: |
| Trash and/or Garbage Overflowing Blockage More Frequent Service Recommended Recommend Inlet / Outlet | 100%- | e Trap Level: |
| Centerwall / Battle Repair Recommend Line Cleaning | 50%- 25%- | |



| Date | 2016-06-16 |
|-------------------------------|--|
| Manifest | WC-06162016-VV-SC |
| Driver's Name | Sergio Cortes |
| Driver's Signature | |
| Recieving Facility | 2586 Shenandoah Way, San Bernadino, CA San Bernadino (Division W) |
| Restaurant Name | <u>Victor Valley Waste Water</u> |
| Restaurant Rep | EUGENE A |
| Restaurant Rep Signatur | е |
| | $oxedsymbol{\square}$ Generator not available for Signature |
| Address: 20111 SHAY RC | OAD VICTORVILLE, CA |
| | |
| Grease Trap Size | |
| Grease Trap Size Comments: | |

Empty-