


Technical drawing of a mechanical assembly, likely a pump or valve, showing a cross-section view (A-A) and a detailed view of the internal components. The drawing includes numerous numbered callouts (1-66) and a list of parts on the right side.

Parts list (from top to bottom):

- 35
- 36
- 37
- 86
- 38
- 39
- 40
- 41
- 42
- 14
- 43
- 44
- 47
- 48
- 49
- 50
- 51
- 52
- 53
- 17
- 54
- 56
- 55
- 57
- 58
- 59
- 60
- 61
- 62
- 63
- 64
- 65
- 66



1. 调整件49的位置,使油动机在关闭位置时,指针指在零位。
2. 油动机行程见《安装使用说明书》。

NOTES:

1. In assembly, adjust pointer bar 60's position to set pointer to zero, with the servomotor in OFF position.
2. The servomotor's travel is shown in INSTALLATION AND OPERATION MANUAL.

				油动机	
标记	处数	更改文件号	签字	日期	
设计	石永昌	审定		20211009	重量(Kg) 412
校核	盛勇	日期			
审核	孙海	日期			
青岛捷能汽轮机集团股份有限公司					
QINGDAO JIENENG STEAM TURBINE GROUP CO.,LTD					