




I
2:1



II
2:1



技术要求

1.安装千分表用通孔根据千分表大小配钻,钻孔位置处加以标记.千分表电厂自备.

2.转子按联轴器找中心时,图示工具应在联轴器圆周方向相隔180°的位置上对称安装两件,下半可只在端面位置装千分表.

Notes

1.The clearance holes for micrometer gauge is drilled depending on the size of micrometer gauge,and the drilled position is marked. The micrometer gauge is prepared by power plant.

2.The tools marked in fig. should be mounted symmetrically at the 180° position from the circle of coupling as the following alignment of two couplings, and for the lower half,the micrometer gauge could be mounter on the head face only.

设　计	
王振兴	
校　对	
王强	
日　期	
19.07	

标记	处数	更改文件号	签　字	日　期
设　计		王振兴	主　管	
校　对		王强	标准审查	
审　核			审　定	
工艺审查			日　期	20190716

联轴器找中心工具
Alignment tools for two couplings

0-0924-0027-0000-00

图样标记	重量(WEIGHT)	比例(SCALE)
	1.26	1:1.5

共　1　页　　第　1　页

青岛捷能汽轮机集团股份有限公司
QINGDAO JIENENG STEAM TURBINE GROUP CO.,LTD