

Quarterly quality report, Q1 2026

Warranty claims received: 44, of which 31 headset creak (see February meeting).

Each bearing swap costs us about EUR 40 in parts and dealer labour.

Average answer time: 3.2 working days against the 5-day promise.

Paint defects on Meridian 3 pre-series: 2 of 40 frames, both orange peel on the down tube, traced to booth humidity on 3 March.

The attached page is the scanned inspection sheet from the paint line.

PAINT LINE INSPECTION SHEET

Week 10, booth 2

Frame	Colour	Result
-------	--------	--------

HBW-M3-2026-00801	Signal orange	pass
-------------------	---------------	------

HBW-M3-2026-00802	Signal orange	orange peel, down tube
-------------------	---------------	------------------------

HBW-M3-2026-00803	Slate	pass
-------------------	-------	------

HBW-M3-2026-00804	Signal orange	orange peel, down tube
-------------------	---------------	------------------------

Booth humidity 71%, above the 60% limit

Inspector: M. Solheim