

Halcyon Bicycle Works

Customer Service

Kiel, 24 February 2026

Dear Ms. Aaltonen,

Thank you for your letter of 14 February about the creaking noise from your Meridian 3 headset. This is covered by the frame warranty. Please bring the bike to your dealer, who will replace the headset bearings and check the fork steerer for wear. The bearing replacement, normally EUR 40, is at no charge.

We are sorry for the trouble.

Kind regards,

Jonas Berg, Customer Service