

Fusion Sketch Cheat Sheet

COLOR KEY

Blue = Not done (moves)

Black = Done (fully constrained)

Purple = Linked (projected)

Green = Locked (Fix – use sparingly)

Yellow = Selected

Red = Error

Orange = Active profile

White dots = Endpoints

10-SECOND SKETCH CHECK

1. Any BLUE? → Not finished
2. Drag test → Moves = missing constraint
3. Any GREEN? → Probably hiding a problem
4. Any PURPLE? → Depends on other geometry
5. All BLACK? → Good to go

WHAT YOU'RE MISSING (MOST LIKELY)

Floating → Coincident

Tilted → Horizontal / Vertical

Off center → Symmetry / Midpoint

Wrong size → Dimension / Equal

Not touching → Coincident / Tangent

COMMON MISTAKES

“Looks right” but still BLUE

Using FIX (green) instead of constraints

Forgetting symmetry

Not defining design intent

GOLDEN RULE

Black = predictable

Blue = risky

Green = workaround

Purple = dependent

GOAL

All BLACK (except purple references)

Nothing moves when dragged